SURVEY & SURVEY & REMONUMENTATION APR 0 7 1998 Remonumentation corner under P.A. 345, Michigan	
ALMIRA TWP. For comers in SECTION LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970	
BENZIE Located In: Corner Code #	LIBER 2 PAGE 157 STATE OF NICHIGAN BENZIE COUNTY
1, Public Land Survey	RECORDED 19 Jan 1998 2:47:21 PM MICHELLE R. GRAY
2. Property Controlling S T R	REGISTER OF DEEDS # PAGES ONE Register of Deeds Stamp & File Number
4. Lot No, Recorded Plat	A B C D E F G H I J K L J
1. Matthew T. Mokanyk , in a field survey on December 29 , 1997 do hereby certify that use requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above we conformance with regulations and rules therefore as required in the current manual of survey instructions of United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law are that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumer re-monumented, recovered, found as expressed below:	3 inder inder inder in 4 7 8 9 10 11 12 inder in the ind for inigan inted, 7
GC# 97480.01 NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.	8 19 20 21 22 23 24 9 10 30 29 28 27 26 25 11
A. Description of original monument and accessories and/or subsequent restoration: August 1850 - GLO Surveyor- set post and two accessories: N1W 26lk, 10" Beech S64W 72lk, 12" Hemlock	12 31 32 33 34 35 36
August 1965 - Norton, Gourdie, Miller & Batzer - set iron - No Witdness	
\$37E - 16.13' - Elm 18"	Ratified by Peer Group In accordance with P.A. 345 Chairman 1000 - 2000
N65W - 43.62 - Bass Wd. 12" S68W - 21.92 - Maple 20" South - 1.47 - Maple 6" North - 9.62 - Old W.T. Stump & Tag	Date 12/22/97 0
B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: 1997 Gosling Czubak Remonumentation- Found 1/2" pipe 18" long. Benzie County Peer Group accepted position of 1/2" pipe for corner G3. Removed ½ " pipe and set standard Benzie County Remonumentation Monument.	
C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: G-3 (SW corner of Section 3, T27N-R13W) Set standard Benzie County Remonumentation Monument: South 1.47' to nail/tag 6" Maple	
N72W 43.51' to nail in NE face 14" Basswood N29E 12.33' to nail in NW face 4" Maple S20E 33.20' to nail in NE face 22" Maple	MATTHEW * MOKANYK PROFESSIONAL * SURVEYOR

Signed by Matchew Mindany Date_