SURVEY & REMONUMENTATION			h is summaring
APR 1 4 1998		•	•
		LIBER 2	PAGE 74
SECTION LAND COPIER RECO	RDATION CERTIFICATE	_	
Filing Requirement of	Act 74, Mich. P.A. 1970	.	STATE OF MICHIGAN
For corners in BENZIE Located In: Corner Code #			BENZIE COUNTY RECORDED
Located In: Corner Code #		11	5 Jan 1998 4:08: 58 PM
1. Public Land Survey T_27N R_14N F-9		1,	HICHELLE R. GRAY
TR			REGISTER OF DEEDS
τ <u> </u>			
2. Property Controlling S T R			
3. Miscellaneous S T R Property in Sec. S T R			,
110bety #1 dec	<u>. </u>	Register of Dee	eds Stamp & File Number
4. Lot No, Recorded Plat			
5. Private Claims	1	A B C D E	F G H I J K L M
	2	5	-4-3-2-1-
I, <u>CARL T. KIISKILA</u> , in a field survey on <u>JANUARY 11</u> 19 96 requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lin	do hereby state that under 4	1-1-8-	- 9 - 10 - 11 - 12
conformance with regulations and rules therefore as required in the current manual of United States Department of the Interior, Bureau of Land Management or by a decre	f survey instructions of the		
that the corner points mentioned in lines 3, 4 and 5 above were in conformance with Board of Land Surveyors or by a Decree of a Court of Law; established, re-e	n the rules of the Michigan		15 15 14 13
recovered, found as expressed below:	8	1920	-21 -22 -23 -24
NOTE: Not more than 2 corners, all in the same town and range, may be re on this certificate.	ecorded 9	30 39	•
	11		28 27 28 23
	12	31-32-	-33343536-
A. Description of original monument and accessories and/or subsequent	restoration:	<u> </u>	
6.L.D. SET POST - SUGAR 12 S13°W 20 (13.2'), SUGAR 12 N38°E 22 (14 R. MAX HARRIS - JOB #83-2-331, JULY 11, 1991 - FOUND 3" ANGLE IRON 5" MAPLE 577°E 18.10', 10" MAPLE N60°E 40.70'.		MAPLE \$10°E 13.1	0',
			·
B. Description of corner evidence found and/or method applied in restor	ing or reestablishing corner:		,
F-9 FD ANGLE IRON FOR N1/4 CORNER 5-28 AS USED BY P.S. MAX HARRIS FOR 9 FENCE REMAINS TO N & W.	SUB'D. OF S-21, JOB #83-2-3	331. CORNER 15 11	N APPROX. LINE W/OLD
	Ratified by Peer Gi		•
	Chairman	- Her	
·	Date 1124196		
C. Description of monument for corner and accessories established to pe	rpetuate locating the position	of the corner:	eccusy,
FD 3"x 2"x 24" ANGLE IRON, REPLACED W/BENZIE CO.			STATE OF MICHIGAN
REMON MON AND SET CARSONITE POST. \$10" S.MAPLE N50°W 2.14'		j	CARL KIISKILA
#13" S.MAPLE N55°E 40.70' # 5" S.MAPLE S77°E 17.97'		3.	LAND *
\$11" S.MAPLE \$10°E 13.03"		3	No.

CHISED LAND SURVE 1= PS, M.HARRIS 1991 WIT. 4-9-97 Date 33981 Surveyor's Michigan License No.___