## SURVEY & REMONUMENTATION

MAR 1 3 1998

STATE OF MICHIGAN

SECTION

BRANCH COUNTY REMONUMENTATION CORNER Ch County
LAND CORNER RECORDATION CERTIFICATE Corded

|   |   | RECORDATION CERTI   |                             |  |
|---|---|---|-----------------------------|--|
| For corners in  | Filing Requirem   | ent of Act 74, Mich. P.   | 10-22-1997 O                | 9:54:04  |
| BRANCH  | Located In:   | Corner Code #   | Linda Lee Mo<br>REGISTER OF | rrison-Mathews   |
| (County) BETHEL TWP.  1. Public Land Survey   | TR  | G-3   |                             | 03 <sub>Page</sub> 0143  |
| 2. Property Controlling S in Section S 3. Miscellaneous S Property in Sec. S  | TR  |   | Register of D               | eeds Stamp & File Number   |
| 4. Lot No, Recorded Pla<br>5. Private Claims  |   |   | A B C D  1 2 6 5 3          | E F G H I J K L I  |
| hereby state that under requirements of P. lines 1 and 2 above were in conformance manual of survey instructions of the United or by a decree of a Court of Law and /or the conformance with the rules of the Michigal established, re-established, monumented, re- | A. 74, Michigan P.A. of 197 with regulations and rules the States Department of the Inte at the corner points mentione in Board of Land Surveyors o | O, the comer points mentioned<br>nerefore as required in the curr<br>prior, Bureau of Land Managem<br>d in lines 3, 4 and 5 above were<br>or by a Decree of a Court of Li | ent 6 18 17 ent 7           | 16 -15 -14 -13 - 14 -13 -14 -13 - 14 -13 -14 -14 -13 -14 -14 -13 -14 -14 -13 -14 -14 -13 -14 -14 -13 -14 -14 -14 -14 -14 -14 -14 -14 -14 -14 |
| NOTE: Not more than 2 corners, all i on this certificate.   | n the same town and ran   | ge, may be recorded   | 10 30 29 11 12 31 32        | 33 34 35 36  |
| A. Description of original monument<br>1826: WM BROOKFIELD, DEPT.<br>1869: J.H. BENNETT, DEPT. CO.<br>GLASS AND BRICK   | SURVEYOR - SET C  | ORNER   | SURVEY PEE<br>CORNER UND    | BY THE BRANCH COUNTY<br>R GROUP AS THE OFFICIAL<br>ER MICHIGAN PUBLIC ACT 345<br>T A MEETING HELD ON   |
| 1954: E.R. REED, CO. SURVEYOR - DUG OVER CONSIDERABLE AREA FOR STONE, UNABLE TO LOCATE  |   |   | R 🐔                         | <i>R. Rood , P.S. Cookep</i><br>E.R. REED  |
| 1973: D. BOONE, SURVEYOR - I<br>1981: E.R. REED. CO. SURVEYO<br>REBAR IRON, RECORDED<br>B. Description of corner evidence of  | FOUND STONE DOW<br>OR - STONE NOW GO<br>O IN LCRC # II-31   | NE, RESET CORNER  | FROM BOONE'S W              | TNESS, SET 1/2" X 30"  |
| SET REMON CAP ON TOP OF E   | XISTING ½" REBAR I  | RON IN CI-MONUMEN   | T BOX 4" BELOW G            | RAVEL ROAD GRADE   |
| C. Description of monument for o  |   |   |                             | the dorper   |
| 1/2" REBAR IRON WITH REMON  | CAP IN CI-MONUME  | NT BOX  | 37.74                       | W. REED  |
| NW CORNER OF SQUARE CON<br>NAIL N. SIDE 12" ASH, S65E 49.<br>14" WALNUT, S70E 100.3' TO CI<br>C/L ROAD, NORTH 27.3'   | 22'<br>ENTER  |   | FE                          | LAND<br>URVEYOR<br>NO.<br>35985  |
| 20" MAPLE, N05W 193.6' TO CE<br>AND IS ACCEPTED AS A CARE   | NTER FUL AND FAITHFUL I   | PERPETUATION OF TH  | E POSITION OF TH            | IE ORIGINAL CORNER   |
| Signed by Ellen WX  | duf   |   | DateS                       | EPTEMBER 3 , 1997  |
| EDWARD W. REED  |   |   |                             |  |
| Surveyor's Michigan License No.   | 33985   |   |                             |  |

ţ