

CALHOUN COUNTY REMONUMENTATION  
LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

APPROVED  
Date Sept 20 1995  
CALHOUN COUNTY  
REMONUMENTATION.

or corners in

Calhoun  
(County)  
Clarendon Twp.  
Public Land Survey T 4 S R 5 W T-8  
T R  
T R  
T R  
Property Controlling S T R  
in Section S T R  
Miscellaneous S T R  
Property in Sec. S T R  
Lot No. , Recorded Plat  
Private Claims

STATE OF MICHIGAN  
CALHOUN COUNTY  
RECORDED

22 SEP 95 10:05 A.M.

Register of Deeds Stamp & File Number  
ANNE B. NORLANDER

CLERK - REGISTER OF DEEDS

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

Frederick J.

Cutcher, in a field survey on September 18, 19 95,  
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned  
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the  
current manual of survey instructions of the United States Department of the Interior, Bureau of Land  
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5  
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a  
Court of Law; established, re-established, monumented, re-monumented, recovered, found as  
expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded  
on this certificate.

Description of original monument and accessories and/or subsequent restoration:

Original Government Survey, December 1825: W. Oak 12" S 35° E 7 lks.; W. Oak 13" N 46-1/2° W  
68 lks.

Lewis, 1882: Set lg. stone w/small ones around.

D. Davis, 11/1981: 16" R. Oak S 80° W 30.4'; 24" Burr Oak S 45° W 37.75'; 18" Maple  
N 40° E 76.5'.

Survey by F. Cutcher, 9/24/87 referenced to W. 1/4 Post, Section 23: 1/2" dia. iron in  
centerline of road; 16" Oak S 80° W 30.4'; 24" Burr Oak S 45° W 37.75'; 18" Maple N 40° E  
76.5'

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 1/2"x6" iron rod at road surface 6" West of centerline N/S road.

Three of above references were found.

REMONUMENTATION

FEB 22 1996

COMMISSION



Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Replaced 1/2"x6" iron rod with county issue Bernsten marker in monument box and is  
accepted as a careful and faithful reestablishment of the position of the original corner.

6" West of centerline N/S road.

S.W. corner house foundation N 45° E 95.30'.

Nail & spotter 10" Oak N 17° W 77.63'.

Nail & spotter 30" Oak S 80° W 30.47'.

N.W. corner bottom cement fence post S 80° E 34.50'.

LIBER 1822 PAGE 48

Signed by Frederick J. Cutcher  
Frederick J. Cutcher

Date September 19, 1995

Surveyor's Michigan License No. 24592