

CALHOUN COUNTY REMONUMENTATION  
LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

APPROVED  
Date Oct 18 1995  
CALHOUN COUNTY  
REMONUMENTATION.

For corners in Calhoun Located In: Corner Code #  
(County)

1. Public Land Survey T 4S. R 7W. L-9  
T      R       
T      R       
T      R       
2. Property Controlling S      T      R       
in Section S      T      R       
3. Miscellaneous S      T      R       
Property in Section S      T      R     

STATE OF MICHIGAN  
CALHOUN COUNTY  
RECORDED

26 OCT 95 10:00 A.M.

Register of Deeds Stamp & File Number

4. Lot No.           , Recorded Plat             
5. Private Claims           

I, Michael A. Groat, in a field survey on September 25, 19 95,  
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned  
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current  
manual of survey instructions of the United States Department of the Interior, Bureau of Land  
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and  
5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a  
Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found  
as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded  
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

1826 Clark Lewis 1882  
9" Beech S 76°E 13½ Links Set stone  
5" Lymr N 86°W 25 Links 14" Butternut S 81°E 8½ Links  
Located by bisecting

BURLINGTON													A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5					4		3		2		1											
3																									
4	7		8					9		10		11		12											
5																									
6	18		17					16		15		14		13											
7																									
8	19		20					21		22		23		24											
9																									
10	30		29					28		27		26		25											
11																									
12	31		32					33		34		35		36											
13																									

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Dug at occupation. Found several rocks with a couple being large and pointed.  
Possibly the one Lewis set in 1882.  
Ran traverse from the Northwest to Northeast corners of section 25. Line fell  
4 feet South of occupation and distance fell 2 feet West of a fence to the South.  
Dug at the point that was mid-way on line and found nothing.  
Set the corner at mid-way distance on the occupation line since this is where  
the large rocks were found.

LIBER 1828 PAGE 34

REMONUMENTATION

FEB 22 1996

COMMISSION

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set Berntsen monument and carsonite marker, from which:  
Nail and spotter in 12" Hickory, S 85°W, 9.8 feet  
Nail and spotter in 6" Hickory, S 28°E, 12.2 feet  
Nail and spotter in 36" Hickory, N 85°W, 30.2 feet  
Nail and spotter in R.R. tie fence pcst, East 2.0 feet



Signed by Michael A. Groat  
Surveyor's Michigan License No. 39079

Date 10-2-95