

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T 41 NR 5 - 6 East

Chippewa COUNTY
Drummond Island

DESCRIPTION OF CORNER Section corner for sections 6 - 7 - 1 - 12

DESCRIPTION OF CORNER MONUMENT 1" pipe with 4" brass cap

WITNESSES TO CORNER 5-15-58

8" cedar S 43°, W 17½ links. Marked "S12NE1"

7" cedar S 56°, E 40 links. Marked "S7NE1"

6" cedar N 51°, W 16 links. Marked "S1NE1"

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR

RESTORED. Replaced from one cedar bearing tree, bearing S 37°, E 15 links. Bearing tree in fair condition. Scribe marks plain. Names Trombley and Schultz appear on bearing tree. Found corner with C. Schultz, P. Milligan and W. Lehman, District Forester. Placed location poster 21.00 chains north on road.

SURVEYORS SEAL

SIGNED *Billy D. Buckler*
Billy D. Buckler
REGISTERED LAND SURVEYOR DATE 6-17-59