

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in
Chippewa

(County)

Located In:

Corner Code ~~##~~

1. Public Land Survey	T 42N R 2E	86
	T R	
	T R	
	T R	
2. Property Controlling in Section	S 7 T 42N R 2E	16
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat
5. Private Claims

16 Oct 10 2005
86 Sep 01 2005

I, Stephan J. Szyszkoski, in a field survey on _____, 19_____, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6													
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

(86) Center of Section 18. Not established in the original survey. Found no subsequent record.
(16-Sec. 7) East 1/16 corner between Sections 7 and 18. Not established in the original survey. Found no subsequent record.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(86) Established the corner at the intersection of straight lines connecting opposite 1/4 corners.
(16-Sec. 7) Established the corner midway and on the section line between Section corner and Quarter corner 1336.27' East and West.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(86) Set 1"IDx36" I.pipe with 4" alum.
MDNR cap. Set measuring nails in:
10" W.Birch N64E 22.5' mrkd "CS BT"
10" W.Birch S76E 24.2' do
6" W.Birch S23W 22.87' do
14" W.Birch N68W 31.9' do
Bearings are magnetic. Distances are to
nail with tag.

(16) Set 1"IDx36" I.pipe with 4" alum.
MDNR cap. Set measuring nails in:
6" Balsam S34W 13.34' mrkd "E1/16 BT"
10" W.Birch S50W 45.0' do
12" Spruce S75E 41.9' do
12" Spruce N17W 14.1' do
Bearings are magnetic. Distances are to
nail with tag.



Signed by

Stephan J. Szyszkoski

Date

1/10/06

Surveyor's Michigan License No. 33986
For the Michigan Department of Natural Resources