## MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

## LAND CORNER RECORD

T\_42NNR\_5E\_\_\_

				Chippewa Drummond	Island	COUNTY
DESCRIPTION	OF	CORNER	1/4 corner	between_Sec.	в <u>. 19<del>-</del>3</u> 0	. <b></b>
DESCRIPTION	OF	CORNER	MONUMENT	l" pipe with	4" brass cap	
WITTNESSES	то			מַאיי.	I"	
			3" W. Bir	ah S_1	5°_E	_ 31_links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Set 1/4 corner by proportionate distance between meander corner and section corner.

No evidence of original corner.

Found old stake and iron pin on ground.

SURVEYORS SEAL

SIGNED Silly D. Suckles DATE 7/23/57