

SECTION

Corner Code ~~##~~

94 JUL 22 AM 11: 11

J. Roger Madsen
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

- | | | | | | | |
|----|---|---|------------|---|-----------|------------|
| 1. | Public Land Survey $\frac{1}{4}$ Corner | T | <u>43N</u> | R | <u>1E</u> | <u>A-8</u> |
| | | T | | R | | |
| | | T | | R | | |
| | | T | | R | | |
| 2. | Property Controlling | S | | T | R | |
| | in Section | S | | T | R | |
| 3. | Miscellaneous | S | | T | R | |
| | Property in Sec. | S | | T | R | |
| 4. | Lot No. _____, Recorded Plat _____ | | | | | |
| 5. | Private Claims _____ | | | | | |

[illegible]

A. Description of original monument and accessories and/or subsequent restoration:

(A-8) From MDOT notes, 4-25-91: Found 1/2" bent re-rod & witnesses prior to road const.

1992: Neil Hill found 1/2" rerod, adjusted & accepted (L.7, P.356).

N 40 E	108.74'	Power Pole
S 70 W	78.95'	Power Pole
N 85 E	72.35'	Conc. R/W Marker
S 55 E	91.23'	Fence Post

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

[A-8] Found corner and accessories as recorded in Liber 7, Page 356 of the Chippewa County Records. Accepted corner position as found.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(A-8) $\frac{1}{2}$ " re-rod & cap 27447 in monument box.

Witnesses:

N 40 E	108.74'	Power Pole
S 70 W	78.95'	Power Pole
N 85 E	72.35'	Conc. R/W Marker
S 55 E	91.23'	Fence Post



Signed by Kurt R. Watson

Date 7-22-94

Surveyor's Michigan License No. 33142

NOTE: Bearings are compass bearings corrected for declination. FORM A

Distances are to a nail in side of witness objects unless noted.

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1971
REVISED JAN., 1981

LIBER 8 PAGE 316