

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Chippewa

(County)

Located in:

Corner Code #

1. Public Land Survey

T\_\_\_ R\_\_\_  
T\_\_\_ R\_\_\_  
T\_\_\_ R\_\_\_  
T\_\_\_ R\_\_\_

2. Property Controlling  
in Section

S 22 T 44N R 1E 14  
S 22 T 44N R 1E 13

3. Miscellaneous  
Property in Sec.

S\_\_\_ T\_\_\_ R\_\_\_  
S\_\_\_ T\_\_\_ R\_\_\_

Register of Deeds Stamp & File Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_  
5. Private Claims \_\_\_\_\_

Jan 04 2007

I, Stephan J. Szyszkoski, in a field survey on \_\_\_\_\_, 19\_\_\_\_ do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

(14-Sec. 22) South 1/16 corner between Sections 22 and 23. Not established in the original survey.  
(13-Sec. 22) East 1/16 corner, Section 22. Not established in the original survey.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(14-Sec. 22) Established the corner midway and on the Section line between Quarter corner 1328.12' north and Section corner 1328.12' south. From the position thus established, the intersection of unmaintained fences west and south is N73W 16' distant.  
(13-Sec. 22) Established the corner at the intersection of straight lines connecting opposite 1/16 corners.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(14) Set 1"IDx36" I.pipe with plastic cap stamped "MICH DNR PS 33986". Set measuring nails in:

6" Cedar S57W 29.5' mrkd "S1/16 BT"  
5" Cedar N27E 23.95' do  
8" Cedar N77E 8.15' do  
7" Cedar S49E 13.8' do

Bearings are magnetic. Distances are to nail with tag.

(13) Set 1"IDx36" I.pipe with plastic cap stamped "MICH DNR PS 33986". Set measuring nails in:

6" Balsam N37W 20.55' mrkd "SE1/16 BT"  
16" Cedar N62E 56.15' do  
14" Spruce S22E 24.13' do  
8" Balsam N29E 12.55' do

fence post S58E 16.5' no nail/tag  
Bearings are magnetic. Distances are to nail with tag, unless noted.



Signed by Stephan J. Szyszkoski  
Surveyor's Michigan License No. 33986

Date 1/9/07

For the Michigan Department of Natural Resources