

**SURVEY &  
REMONUMENTATION**

CHIPPEWA COUNTY REMONUMENTATION CORNER

APR 26 1995

COMMISSION

**LAND CORNER RECORDATION CERTIFICATE**

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in  
Chippewa

(County)

Located In:

Corner Code #

- |                         |   |     |    |     |
|-------------------------|---|-----|----|-----|
| 1. Public Land Survey   |   | 44N | 1W | F-1 |
|                         | T |     | R  |     |
|                         | T |     | R  |     |
|                         | T |     | R  |     |
|                         | T |     | R  |     |
| 2. Property Controlling | S |     | R  |     |
| in Section              | S |     | R  |     |
| 3. Miscellaneous        | S |     | R  |     |
| Property in Sec.        | S |     | R  |     |

\$ 7.00 LAND CORNER

\$ 2.00 MSSR

24 OCT 94 3:45 P.M. RECEIPT# 831

RECEIVED FOR RECORD

CHIPPEWA COUNTY - STATE OF MICHIGAN  
SHARON H. KENNEDY, REGISTER OF DEEDS

Register of Deeds Stamp & File Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_
5. Private Claims \_\_\_\_\_

Keith R. Waters

June 21

94

I, \_\_\_\_\_, in a field survey on \_\_\_\_\_, 19\_\_\_\_, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

**NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.**

- A. Description of original monument and accessories and/or subsequent restoration:

F-1 North 1/4 Corner of Section 4, T44N, R1W

Corner was not set in the original survey. Found no evidence of subsequent establishment.

- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

F-1 (T44N, R1W)

This corner is being established as part of the Chippewa County Remonumentation Program.

Established corner on township line midway between closing corner common to Sections 4 & 5, T44N, R1W, and common corner to Sections 3 & 4, T44N, R1W, and Sections 33 & 34, T45N, R1W. Corner falls approximately 40 feet south of an east-west 2-track road. A concrete monument at the South 1/4 corner of Section 33 is 6.60 feet west of this corner.

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

F-1 (T44N, R1W)

Corner is a 3/4" x 24" rebar with 3 1/4" aluminum Chippewa County Remonumentation cap approximately 40 feet south of an east-west 2-track road. Witnesses:

7" Red Pine, S50°E 28.62'  
10" Red Pine, S19°W 43.38'  
14" White Birch, S69°W 84.10'  
10" White Pine, S88°W 53.32'  
Concrete Monument (S 1/4 Corner of  
Section 33), WEST 6.60'

Note: Distances are to a nail and tag in the side of the witness object. Trees are blazed and painted. Bearings are compass bearings corrected for declination.

Signed by Keith R. Waters  
33142

Date 10-18-94

Surveyor's Michigan License No. \_\_\_\_\_

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS JAN. 25, 1971  
REVISED MAY 14, 1975  
REMONUMENTATION  
REVISED JAN. 1983

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

