

SURVEY &
REMONUMENTATION

APR 07 1998

Chippewa County Remonumentation Corner
LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

SECTION

Chippewa

Located In:

Corner Code #

1. Public Land Survey

T 45N R 1E C-2

T R

T R

T R

2. Property Controlling
in Section

S T R

S T R

3. Miscellaneous
Property in Sec.

S T R

S T R

4. Lot No. , Recorded Plat

5. Private Claims

\$7.00 LAND CORNER

\$2.00 MSSR

14 Jan 1998 3:17:15 PM Receipt #5566

RECEIVED FOR RECORD

CHIPPewa COUNTY - STATE OF MICHIGAN

SHARON H. KENNEDY, REGISTER OF DEEDS

BOOK 10 PAGE 111
Register of Deeds Stamp & File Number

I, Larry R. Rogers, in a field survey on October 22, 1997, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(C-2) 1/4 Corner Common to Sections 5 and 6, T.45 N., R.1 E.


Original corner post was placed in September, 1845 by James H. Mullett. Numerous Section drawings in County Surveyor files indicate presence of corner and give distances North and South to Section Corners. Corner was restored in 1995 survey by Larry R. Rogers, P.S. 29251, on line between Section corners to North and South at prorated County Surveyor distances.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(C-2) 1/4 Corner Common to Sections 5 and 6, T.45 N., R.1 E.

This corner is being re-established as part of the Chippewa County Remonumentation Program.

Found 3/4" iron pin with plastic Chippewa County Remonumentation cap in North-South gravel road from Rogers' survey. Accepted corner position as found and established four witnesses.



C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(C-2) 1/4 Corner Common to Sections 5 and 6, T.45 N., R.1 E.

Corner is a 3/4" iron pin with plastic Chippewa County Remonumentation cap.

Witnesses:	4" White Spruce	N13°W	84.48'
	5" Cedar	S16°W	115.35'
	Fence post	N33°E	39.35'
	Fence post	S36°E	33.73'



Signed by [Signature] Date 19 DEC 1997

Surveyor's Michigan License No. 29251

NOTE: All bearings are compass bearings. All distances are to a nail in side of witness objects unless noted.