

MAR 09 1994

Chippewa County Remonumentation Corner

RECEIVED FOR RECORD  
CHIPPewa COUNTY  
STATE OF MICHIGAN

COMMISSION

LAND CORNER RECORDATION CERTIFICATE

93 DEC 29 AM 10:27

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Chippewa

(County)

Located In:

Corner Code ##

J. Roger Melick

REGISTER OF DEEDS

1. Public Land Survey T 45N R 1E I-13 Standard Corner
2. Property Controlling S T R
3. Miscellaneous S T R
- Property in Sec. S T R

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat
5. Private Claims

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

I, Larry R. Rogers, in a field survey on November 15, 19 93 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

- A. Description of original monument and accessories and/or subsequent restoration:  
(I-13) Standard Corner Common to Sections 34 & 35 (T45N-R1E)  
Original Survey Notes : 24 September 1840, William A. Burt.  
Set Quarter Section Post  
15" Hemlock N35°E 35 links  
18" Hemlock N53°W 29 links

1930 survey by C.M. Cade indicates a wood post 23.1' West of the Closing Corner for Sections 2 & 3, T44N-R1E. The Chippewa County Road Commission found wood post and recorded it in Liber 3, Page 205 of the Chippewa County Corner Records. Road Commission replaced corner with a monument box during reconstruction of Riverside Drive.

- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(I-13) This corner is being perpetuated as part of the Chippewa County Remonumentation Program.

Found 5/8" iron in monument box, 3' West of the centerline of Riverside Drive. Position checks with one remaining Road Commission witness tie (Spruce - Southeast) and falls 23.27' West of the found Closing Corner. Accepted position as found and established two new witnesses.

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner.  
(I-13) Corner is a 5/8" iron in a monument box, 3' West of the centerline of Riverside Drive.

Witnesses: "V" Cut in West End of 20" C.M.P. S46°W 33.12'  
"V" Cut in North End of 20" C.M.P. N56°E 44.03'  
20" Spruce S42°E 52.76'  
Closing Corner (3/4" Iron) East 23.27'



Signed by [Signature]

Date 23 DEC 1993

Surveyor's Michigan License No. 29251

NOTE: Bearings are compass bearings corrected for declination.  
Distances are to a nail in side of witness objects unless noted.