

**LAND CORNER RECORDATION CERTIFICATE**  
**Filing Requirement of Act 74, Mich. P.A. 1970**

For corners in  
Chippewa

(County)

Located In:

Corner Code ##

RECEIVED FOR RECORD  
 CHIPPEWA COUNTY  
 STATE OF MICHIGAN

94 JUL 22 AM 11:15

*J. Roger Malott*

REGISTER OF DEEDS

Register of Deeds Stamp & File Number

1. Public Land Survey

T 45N R 1E K-1

T \_\_\_\_\_ R \_\_\_\_\_

T \_\_\_\_\_ R \_\_\_\_\_

T \_\_\_\_\_ R \_\_\_\_\_

2. Property Controlling  
 in Section

S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_

S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_

3. Miscellaneous  
 Property in Sec.

S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_

S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_

5. Private Claims \_\_\_\_\_

I, Larry R. Rogers, in a field survey on DECEMBER 7, 19 93, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

**NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.**

A. Description of original monument and accessories and/or subsequent restoration:

(K-1) Northeast Corner of Section 2 (T45N-R1E)

Original ties: 10" Cedar N32°W 10 links      10" B. Ash      N40°E      9 links

1990: Keith Waters found and accepted a 1½" pipe (Liber 7, Page 220).

Power Pole (DR1-76E-24M)	S56°E	32.31'
24" White Pine	East	34.57'
6" Balsam Fir	N34°W	65.13'
Street Sign	S42°W	43.95'

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(K-1) Found corner and all accessories as recorded in Liber 7, Page 220 of the Chippewa County Records. Accepted corner position as found.

**SURVEY &  
 REMONUMENTATION**

JUL 26 1994

**COMMISSION**



C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(K-1) Corner is a 1½" iron pipe.

Witnesses:	Power Pole (DR1-76E-24M)	S56°E	32.31'
	24" White Pine	East	34.57'
	6" Balsam Fir	N34°W	65.13'
	Street Sign	S42°W	43.95'

Signed by \_\_\_\_\_

Date 20 JULY 1994

Surveyor's Michigan License No. 29251

**NOTE: Bearings are compass bearings corrected for declination.  
 Distances are to a nail in side of witness objects unless noted.**