

APR 07 1998

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970
Chippewa County Remonumentation Corner

SECTION

For corners in

Chippewa

Located In:

Corner Code #

1. Public Land Survey

T 46N R 2W

T 45N R 2W

T R

T R

S T R

S T R

S T R

S T R

2. Property Controlling
in Section

3. Miscellaneous
Property in Sec.

B-13 Same

B-1 Corner

\$7.00 LAND CORNER

\$2.00 MSSR

12 Mar 1998 12:40:21 PM Receipt #6527

RECEIVED FOR RECORD

CHIPPewa COUNTY - STATE OF MICHIGAN
SHARON H. KENNEDY, REGISTER OF DEEDS

BOOK 10 PAGE 220

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____

5. Private Claims _____

I, William L. Karr, in a field survey on October 31, 1997, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

1	A	B	C	D	E	F	G	H	I	J	K	L	M
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18				16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

A. Description of original monument and accessories and/or subsequent restoration:

(B-13) 1/4 Corner Common to Section 31, T.46 N., R.2 W., and Section 6, T.45 N., R.2 W.

1840 Austin Burt set post in original survey. Witnesses: Fir 10 N36°E 29

Fir 11 N23°W 37

Found no record of subsequent restoration.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(B-13) 1/4 Corner Common to Section 31, T.46 N., R.2 W., and Section 6, T.45 N., R.2 W.

This corner is being perpetuated as part of the Chippewa County Remonumentation Program.

Found no evidence of the original corner or subsequent restoration. Reestablished the corner by single proportionate measurement between Section corner 31, 32, 5 and 6 and the Township corner 31, 6, 1 and 36. Distance East is 2646.99' (meas.) - GLO is 2640'; distance West is 2635.75' (meas.) - GLO is 2628.78'.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(B-13) 1/4 Corner Common to Section 31, T.46 N., R.2 W., and Section 6, T.45 N., R.2 W.

Corner is a 3/4" x 24" iron with stamped Chippewa County Remonumentation Corner cap and falls at the Southeast base of a 2" Twin Ironwood.

Witnesses:	Aspen 12"	N04°E	9.56'
	Balsam 14"	S04°E	58.70'
	Aspen 16"	S46°W	30.19'
	Aspen 12"	West	29.68'
	Top of bank	South	135°±

Signed by William L. Karr

Date 12/24/97

Surveyor's Michigan License No. 27450

NOTE: All bearings are compass bearings corrected for declination (6°W). All distances are to a nail and tag in the side of witness object unless otherwise noted.

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1975
REVISED JAN., 1983
REVISED OCT., 1995

