

SURVEY &
REMONUMENTATION

APR 07 1998

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970
Chippewa County Remonumentation Corner

For corners in SECTION

Chippewa County Located in: Corner Code #

1. Public Land Survey		T45N R2W	G-8
		T R	
		T R	
		T R	
2. Property Controlling	S	T R	
in Section	S	T R	
3. Miscellaneous	S	T R	
Property in Sec.	S	T R	
4. Lot No.			Recorded Plat
5. Private Claims			

47.00 LAND CORNER

42.00 MSSR

6 Mar 1998 1:53:39 PM Receipt #6451

RECEIVED FOR RECORD

CHIPPEWA COUNTY - STATE OF MICHIGAN
SHARON H. KENNEDY, REGISTER OF DEEDS

BOOK 10 PAGE 188

Register of Deeds Stamp & File Number

I, Keith R. Waters, in a field survey on October 31, 1997, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

G-8 1/4 Corner common to Sections 21 & 22, Town 45 North, Range 2 West

1849 - Original corner (spruce post) was established by Harvey Mellen, D.S.

Witnesses: Spruce 6, N74°E 14 links

Yellow Birch 16, S34°W 36 links

1913 - Chippewa County Surveyor Frederick H. Brown notes for Section 21 indicate that the only original corner that he found in this section was the northeast corner. His sketch shows the 1/4 corner midway between section corners 2633 feet north and 2633 feet south. (Note: other notes by Brown show this mile as 5280 feet).

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

This corner is being reestablished as part of the Chippewa County Remonumentation Program.

Found no evidence of the corner. Reestablished corner by single proportionate measurement midway on line between section corners 2636.9 feet north and 2636.9 feet south.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Placed a 3/4" x 24" rebar with a plastic Chippewa County Remonumentation cap at the corner location, which falls approximately 6 feet west of the centerline of a north-south gravel road (Johnson Road).

Witnesses:

1/2" Rebar with cap #33142 on east-west 1/4 line of Section 22, EAST 40.00'

8" Spruce, S30°W 131.82'

3" Poplar, N77°W 46.63'

6" Spruce, S56°W 183.39'

Note: Distances to trees are to a nail/tag #33142 in the side.

Trees are blazed and painted.

Bearings are compass bearings corrected declination.

Signed by

Keith R. Waters

Date

12-30-97

Surveyor's Michigan License No. 33142

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1975
REVISED JAN., 1983
REVISED OCT., 1995

LCRC T45N R2W G-8

BOOK 10 PAGE 188

KDR:SS 12P
11/7/97

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34						
13													

