

SURVEY &
REMONUMENTATION

APR 07 1998

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970
Chippewa County Remonumentation Corner

For corner **SECTION**

Chippewa County	Located in:	Corner Code #
1. Public Land Survey	T45N R2W	H-7
	T R	
	T R	
	T R	
2. Property Controlling in Section	S T R	
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No.		Recorded Plat
5. Private Claims		

47.00 LAND CORNER
42.00 MSSR
6 Mar 1998 1:56:47 PM Receipt #6451
RECEIVED FOR RECORD
CHIPPEWA COUNTY - STATE OF MICHIGAN
SHARON H. KENNEDY, REGISTER OF DEEDS

BOOK 10 PAGE 193

Register of Deeds Stamp & File Number

I, Keith R. Waters, in a field survey on November 7, 1997, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

H-7 1/4 Corner common to Sections 15 & 22, Town 45 North, Range 2 West

1849- Original corner (hemlock post) was established by Harvey Mellen, D.S.

Witnesses: Cedar 9, S45°E 4 links

Hemlock 12, S60°W 3 links

1919 - Chippewa County Surveyor Frederick H. Brown notes for Section 15 indicate that corner could not be found.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

This corner is being reestablished as part of the Chippewa County Remonumentation Program.

Found no evidence of this corner or its accessories. Reestablished corner by single proportionate measurement midway on line between section corners east and west.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Placed a 3/4" x 24" rebar with a stamped aluminum Chippewa County Remonumentation cap at corner location, which falls approximately 45 feet south of an east-west ridge.

Witnesses:

10" Red Maple, N82°W 75.87'

8" Cedar, N17°W 21.58'

20" Red Maple, S18°E 20.62'

10" Spruce, N41°E 75.12'

Note: Distances are to a nail/tag #33142 in the side of the tree.

Trees are blazed and painted.

Bearings are compass bearings corrected for declination.

Signed by Keith R. Waters

Date 12-30-97

Surveyor's Michigan License No. 33142

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1975
REVISED JAN., 1983
REVISED OCT., 1995

BOOK 10 PAGE 193

