

SURVEY &
REMONUMENTATION

APR 07 1998

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970
Chippewa County Remonumentation Corner

For corners in SECTION

Chippewa County	Located in:	Corner Code #
1. Public Land Survey	T45N R2W	L-9
	T R	
	T R	
	T R	
2. Property Controlling in Section	S T R	
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No.		, Recorded Plat
5. Private Claims		

\$7.00 LAND CORNER
\$2.00 MSSR
6 Mar 1998 2:08:26 PM Receipt #6451
RECEIVED FOR RECORD
CHIPPEWA COUNTY - STATE OF MICHIGAN
SHARON H. KENNEDY, REGISTER OF DEEDS

BOOK 10 PAGE 210

Register of Deeds Stamp & File Number

I, Keith R. Waters, in a field survey on November 10, 1997, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

L-9 1/4 Corner common to Sections 24 & 25, Town 45 North, Range 2 West

1849 - Original corner (spruce post) was established by Harvey Mellen, D.S.
Witnesses: Spruce 5, N65°E 26 links - Tamarack 6, S25°W 20 links

Circa 1920 - Chippewa County Surveyor Frederick H. Brown notes for Section 25 indicate "could not find any post"

1974 - LCRC liber 1, page 129, Lawrence R. Feindt, RLS 21566. A sketch of Section 25 on the back said of the LCRC shows this corner midway on line between the found section corner K-9 and section corner M-9, which was mathematically placed at a single proportionate position between found 1/4 corner M-10 and section corner M-7.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

This corner is being reestablished as part of the Chippewa County Remonumentation Program.
Found no evidence of any monument at the corner location. Reestablished corner location as described in above mentioned LCRC. This position has been used for numerous surveys in Section 25, but was never monumented.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Placed a 3/4" x 48" rebar with a stamped aluminum Chippewa County Remonumentation cap at the corner location, which falls in a large swamp, approximately 550 feet north of railroad tracks.
Witnesses:

Power Pole (KAB-36), S40°W 622.21'
Power Pole (KAB-35), S07°W 420.66'
7" White Pine, S01°W 472.74'
Power Pole (KAB-34), S40°E
1/2" Iron w/cap #33142, SOUTH 475.85 (On top of ridge on south side of swamp)

Note: Distances are to a nail/tag #33142 in the side of the witness object.
Bearings are compass bearings corrected for declination.

Signed by Keith R. Waters

Date 12-30-97

Surveyor's Michigan License No. 33142

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1975
REVISED JAN., 1983
REVISED OCT., 1995

BOOK 10 PAGE 210

