

**LAND CORNER RECORDATION CERTIFICATE**  
**Filing Requirement of Act 74, Mich. P.A. 1970**

For corners in  
Chippewa  
 (County)

Located In:

Corner Code #

1. Public Land Survey

T 46N R 1W M-12 Same  
 T 46N R 1E A-12/Corner  
 T \_\_\_\_\_ R \_\_\_\_\_  
 T \_\_\_\_\_ R \_\_\_\_\_

2. Property Controlling  
 in Section

S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_  
 S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_

3. Miscellaneous  
 Property in Sec.

S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_  
 S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_

5. Private Claims \_\_\_\_\_

RECEIVED FOR RECORD  
 CHIPPEWA COUNTY  
 STATE OF MICHIGAN

94 JUL 22 AM 11:14

*J. Roger Melick*

REGISTER OF DEEDS

Register of Deeds Stamp & File Number

I, Keith R. Waters, in a field survey on OCTOBER 25, 19 93, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

**NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.**

A. Description of original monument and accessories and/or subsequent restoration:

(M-12) Location shown on State Highway Plans; file # S-31-C-2

1987: Neil Hill found  $\frac{1}{2}$ " iron and accepted (Liber 7, Page 36).

N60°W	83.98'	Third Post North of Fence Corner
West	75.60'	Top Center Concrete R/W Marker
East	74.25'	Power Pole
S55°E	79.53'	Northwest Corner Top Lip of Northerly Brick Planter

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(M-12) Found corner and all accessories as recorded in Liber 7, Page 36 of the Chippewa County Records. Accepted corner position as found.

**SURVEY &  
 REMONUMENTATION**

JUL 26 1994

**COMMISSION**



C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(M-12) Corner is a  $\frac{1}{2}$ " rod in monument box in line with East-West fence lines.

**WITNESSES**

N60°W	83.98'	Third Post North of Fence Corner
West	75.60'	Top Center Concrete R/W Marker
East	74.25'	Power Pole
S55°E	79.53'	Northwest Corner Top Lip of Northerly Brick Planter

Signed by Keith R. Waters Date 7-22-94

Surveyor's Michigan License No. 33142

**NOTE: Bearings are compass bearings corrected for declination.  
 Distances are to a nail in side of witness objects unless noted.**