

MAY 28 1997

COMMISSION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970
Chippewa County Remonumentation Corner

For corners in

Chippewa County

Located in:

Corner Code #

1. Public Land Survey

T46N R1E

E-9

T R

T R

T R

2. Property Controlling
in Section

S

T R

S

T R

3. Miscellaneous
Property in Sec.

S

T R

S

T R

4. Lot No.

, Recorded Plat

5. Private Claims

\$7.00 LAND CORNER

\$2.00 MSSR

2/28/1997 3:10:09 PM

Receipt #217

RECEIVED FOR RECORD

CHIPPewa COUNTY - STATE OF MICHIGAN

SHARON H. KENNEDY, REGISTER OF DEED

BOOK 9 PAGE 372

Register of Deeds Stamp & File Number

I, William L. Karr, in a field survey on August 28, 1996, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(E-9) Section Corner Common to Sections 20,21,28 & 29, T. 46 N., R. 1 E.

1845 J.H. Mullett set post in Original Survey.

1902 F.H. Brown in records in County Surveyors Office found post set by Carleton for section corner.

1977 Corner Tie Book in County Surveyors Office shows monument and cedar post for corner and ties to fence corners.

1984 W.L. Karr, PS 27450, found no evidence of original corner. Found 3/4" iron 8" below surface in road intersection and accepted for corner. Recorded Liber 6, Page 132, Chippewa County Corner Records.

1992 L.R. Rogers, PS 29251, in a survey in section 21, Northwoods Land Surveying job number 141-37, found 3/4" iron as recorded by Karr 3.5' below surface and raised with a 1/2 x 48" re-bar with cap number 29251.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(E-9) Section Corner Common to Sections 20,21,28 & 29, T. 46 N., R. 1 E.

This corner is being perpetuated as part of the Chippewa County Remonumentation Program.

Found corner as recorded by Karr in 1984 and raised to surface by Rogers in 1992.

Accepted corner position as found.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(E-9) Section Corner Common to Sections 20,21,28 & 29, T. 46 N., R. 1 E.

Corner is a 1/2" x 48" re-bar with plastic cap no. 29251 in road intersection, 4.6' west of centerline of North and South road and 4.4' north of centerline road to West. Corner is 0.5' below grade.

Witnesses:	6" Oak	S 75° E	111.29'
	Power Pole	S 30° E	64.73'
	Power Pole	S 36° W	61.77'
	(DR1/76/15)		
	Fence Post	N 35° W	44.96'

Bearings are compass bearings, corrected for declination, all distances are to a nail and tag in the side of the witness object unless otherwise noted.

Signed by

William L. Karr

Date

12-30-96

Surveyor's Michigan License No. 27450

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971

REVISED MAY 14, 1975

REVISED JAN., 1983

REVISED OCT., 1995