

CHIPPEWA COUNTY REMONUMENTATION CORNER

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Chippewa

(County)

Located In:

Corner Code #

1. Public Land Survey T 46N R 3W K-6
 T _____ R _____
 T _____ R _____
 T _____ R _____
2. Property Controlling S _____ T _____ R _____
 in Section S _____ T _____ R _____
3. Miscellaneous S _____ T _____ R _____
 Property in Sec. S _____ T _____ R _____

\$ 7.00 LAND CORNER

\$ 2.00 MSSR

24 OCT 94 2:25 P.M. RECEIPT# 811

RECEIVED FOR RECORD

CHIPPEWA COUNTY - STATE OF MICHIGAN
SHARON K. KENNEDY, REGISTER OF DEEDS

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, Larry R. Rogers, in a field survey on May 7,, 19 93,
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the
current manual of survey instructions of the United States Department of the Interior, Bureau of Land
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a
Court of Law; established, re-established, monumented, re-monumented, recovered, found as
expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded
on this certificate.

- A. Description of original monument and accessories and/or subsequent restoration:
(K-6) 1/2 Corner Common to Sections 14 & 13, T46N-R3W

1849 Harvey Mellen, set Maple post.
 7" Spruce N36°E 39 links
 10" Tamarack S16°W 27 links

194? County Surveyor Field notes call for a 1" square iron pin.
 6" Poplar N15°E 44.25'
 4" Spruce N66°E 87.05'

- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

This corner is being perpetuated as part of the Chippewa County Remonumentation Program.

Found a 1" square iron 1" above ground and remains of a North-South fence line at corner
location. Accepted corner position as found.

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Corner is a 1" square iron 1" above ground. Corner falls on the remains of a North-South
fence. There is heavy beaver flooding to North, East and West. A small Red Pine
plantation is just to the Southeast of the corner.

Witnesses:

8" Cedar N15°E 51.86'
 4" Tamarack S67°E 6.68'
 12" Red Pine S16°E 35.22'
 4" Tamarack N75°W 7.42'

Signed by

Date

10 OCT 1994

1687-00

Surveyor's Michigan License No.

29251

NOTE: Bearings are compass bearings corrected for declination.
Distances are to a nail in side of witness objects unless noted.

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

SURVEY &
REMONUMENTATION

NOV 07 1994

COMMISSION

