

# SURVEY & REMONUMENTATION

DEC 07 1994

COMMISSION

Chippewa County Remonumentation Corner

## LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Chippewa

(County)

Located In:

Corner Code ##

1. Public Land Survey

T 47N R 2E

I-6/I-7

T R

T R

T R

T R

2. Property Controlling  
in Section

S T R

S T R

3. Miscellaneous

S T R

Property in Sec.

S T R

4. Lot No. , Recorded Plat

5. Private Claims

\$ 7.00 LAND CORNER

\$ 2.00 MSSR

18 OCT 94 1:04 P.M. RECEIPT# 700

RECEIVED FOR RECORD

CHIPPewa COUNTY - STATE OF MICHIGAN  
SHARON H. KENNEDY, REGISTER OF DEEDS

Register of Deeds Stamp & File Number

I, William L. Karr, in a field survey on October 15, 19 93, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

**NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.**

A. Description of original monument and accessories and/or subsequent restoration:

(I-6/I-7) Witness Corner to the Meander Corner Common to Sections 14 & 15 (T47N-R2E)

1845 J.H. Mullett, set post.

6" B. Ash N18°W 37 links

8" B. Ash N41°E 20 links

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(I-6/I-7) This corner is being perpetuated as part of the Chippewa County Remonumentation Program.

Found an old wood post at marshy water's edge. Pulled post and determined it had a sawed flat bottom. Post fell on the extension of a very old fallen fence. Accepted corner position as found and replaced with a 3/4" iron.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(I-6/I-7) Corner is a 3/4" x 48" iron with a 3" diameter aluminum "Chippewa County Remonumentation" cap. Corner falls at marshy water's edge on extension of very old fallen fence line to the North.

Witnesses: 6" Double Ash

6" Triple Ash

10" Quadruple Ash

1/4 Corner Sections 14 & 15 (1" Square Iron)

West

N39°W

N02°W

North

28.73'

17.08'

80.43'

1291.30'

No other ties available.

Signed by

William L. Karr

Date

2/1/94

Surveyor's Michigan License No.

27450

1772-00

NOTE: Bearings are compass bearings corrected for declination.

Distances are to a nail in side of witness objects unless noted.

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971  
REVISED MAY 14, 1975  
REVISED JAN., 1983

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

