

**FEB 23 2001**

**SECTION**

**LAND CORNER RECORDATION CERTIFICATE**  
**Filing Requirement of Act 74, Mich. P.A. 1970**  
**Chippewa County Remonumentation Corner**

For corners in

Chippewa County

Located in:

Corner Code #

1. Public Land Survey

T47N R2E

G-5

2. Property Controlling  
in Section

S  
S  
S  
S

T  
T  
T  
T


R  
R  
R  
R

3. Miscellaneous  
Property in Sec.

4. Lot No.

, Recorded Plat

5. Private Claims



I, Larry R. Rogers, P.S., in a field survey on December 8, 2000, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

**\$7.00 LAND CORNER**

**\$2.00 MSSR**

9 FEB 2001 10:49:02 AM Receipt #1201  
RECEIVED FOR RECORD  
CHIPPewa COUNTY - STATE OF MICHIGAN  
SHARON H. KENNEDY, REGISTER OF DEEDS

BOOK **11** PAGE **243**

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

A. Description of original monument and accessories and/or subsequent restoration:

(G-5) Section corner common to Sections 9, 10, 15 and 16, Township 47 North, Range 2 East.

The original corner post was placed in 1845 by John Mullett. In 1919, County Surveyor F.H. Brown "found the old cross lines... and put in post". In 1981, W.L. Karr, PS 27450 found no evidence of corner position and re-established this corner position "using a combination of proration and local evidence" and filed a LCRC in Liber 5 at Page 10 of the Chippewa County Corner Records.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(G-5) Section corner common to Sections 9, 10, 15 and 16, Township 47 North, Range 2 East.

This corner is being perpetuated as part of the Chippewa County Remonumentation Program.

Found 1/2" iron pin from Karr survey and recovered one witness. Accepted corner position as found and established three new witnesses. Distance to 1/4 Corner to South measures 2677 feet (C.S. = 2705 feet).

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(G-5) Section corner common to Sections 9, 10, 15 and 16, Township 47 North, Range 2 East.

Corner is a 1/2" iron pin with P.S. cap number 16041 on the extension of electric fence to the South and 10 feet North of electric fence to West.

Witnesses:

14" Yellow Birch	N51°E	30.08 feet (existing)
10" Hemlock	S74°E	16.61 feet
10" Hemlock	N71°W	52.41 feet
16" Hemlock	N04°W	35.48 feet

Bearings are magnetic compass bearings. All distances are to a nail and tag in the side of the witness object unless otherwise noted.

Signed by

Larry R. Rogers, P.S.

Surveyor's Michigan License No. 29251

Date

29 DEC 2000