

Chippewa County Remonumentation Corner

RECEIVED FOR RECORD
CHIPPEWA COUNTY
STATE OF MICHIGANLAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

93 DEC 29 AM 10: 26

For corners in

Chippewa

(County)

Located In:

Corner Code ##

J. Roger Malott
REGISTER OF DEEDS

1. Public Land Survey

T 46N R 2W G-1 / H-1 / Same
T 47N R 2W #2 G-13/H-13/Corner2. Property Controlling
in Section

S T R

SURVEY &
REMONUMENTATION3. Miscellaneous
Property in Sec.

S T R

Register of Deeds Stamp & File Number

JUL 22 1993

4. Lot No. _____, Recorded Plat _____

5. Private Claims _____

SECTION

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

William L. Karr

December 9

93

I hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

Description of original monument and accessories and/or subsequent restoration:

(G-1/H-1) Witness Corner to the Meander Corner Section 3 (T46N-R2W) and Section 34 (T47N-R2W)

1840 William Burt, D.S.

Pine 22 for Meander Corner

Original corner position now falls in Waiska Bay. Township Line is shown on a plat of survey dated 3/29/40 (unknown surveyor of the H.M. Edmonds property) and also on the Supervisor's Plat Number 1 of Bay Mills & Superior Townships (5/47) by R.H. Larsen, RLS. Meander corner is not shown on either survey.

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(H-1/G-1) This corner is being re-established as part of the Chippewa County Remonumentation Program.

Found no evidence of original corner (falls in Waiska Bay). Recovered several monuments from Supervisors Plat of Bay Mills And Superior Townships. Reconstructed shore traverse line from plat and point of intersection of Township line with the plat line. Checked angles at 1/4 corner common to 3 & 34 and also where Township line crosses road shown on the plat. Angles check very closely with the plat and the Edmonds survey. Established Witness Corner to Meander Corner on plat shore traverse line as the position was indicated in 1947.

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(H-1/G-1) Corner is a 3/4" x 48" iron with stamped aluminum cap, P.S. #27450. Corner falls on beach, 26' South of water's edge.

Witnesses: Top Northwest corner metal retaining wall	S53°W	74.89'
Top Northeast corner metal retaining wall	S85°E	29.81'
7" White Birch	S38°E	44.73'
12" Spruce	S12°W	62.23'

ed by *William L. Karr*

Date 12/14/93

Surveyor's Michigan License No. 27450

NOTE: Bearings are compass bearings corrected for declination.
Distances are to a nail in side of witness objects unless noted.

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1975
REVISED JAN., 1983

L. 8 Pg 127 Other code: 2