

DEC 16 1999

SECTION

# LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970  
Chippewa County Remonumentation Corner

\$7.00 LAND CORNER

\$2.00 MSSR

21 JAN 1999 11:09:13 AM Receipt #13123

RECEIVED FOR RECORD

CHIPPEWA COUNTY - STATE OF MICHIGAN  
SHARON H. KENNEDY, REGISTER OF DEEDS

BOOK 10 PAGE 375

Register of Deeds Stamp & File Number

For corners in

Chippewa	Located In:	Corner Code #
1. Public Land Survey	SAME CORNER { T 48N R 1E M 11/12 ✓ T 48N R 2E A 11/12	#1
2. Property Controlling in Section	S T R	
3. Miscellaneous Property in Sec.	S T R	

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_  
5. Private Claims \_\_\_\_\_

I, Larry R. Rogers, in a field survey on December 22, 1998, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A	B	C	D	E	F	G	H	I	J	K	L	M
1												
2	6		5		4		3		2		1	
3												
4	7		8		9		10		11		12	
5												
6	18		17		16		15		14		13	
7												
8	19		20		21		22		23		24	
9												
10	30		29		28		27		26		25	
11												
12	31		32		33		34		35		36	
13												

A. Description of original monument and accessories and/or subsequent restoration:  
(M-11/12) Meander Corner on East Line of Section 36, Township 48 North, Range 1 East.  
The original corner was placed in 1845 by John Mullett 11.00 chains North of 1/4 post. Found no reference to corner in County Surveyor notes. In 1992, William L. Karr, P.S. 27450, set witness corner to Meander Corner 45 feet South of shore of St. Mary's River on the extension of the Range Line to South. Corner falls 65.06 feet North of record G.L.O. position. Karr filed a L.C.R.C. in Liber 9, Page 12 of the Chippewa County Corner Records.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:  
(M-11/12) Meander Corner on East Line of Section 36, Township 48 North, Range 1 East.  
This corner is being perpetuated as part of the Chippewa County Remonumentation Program. Found 1/2" iron pin with stamped aluminum cap as recorded by Karr. Corner position was accepted as a Witness Corner to the Meander Corner because distance South to 1/4 Corner is 65 feet longer than record G.L.O.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:  
(M-11/12) Witness Corner to the Meander Corner on East Line of Section 36, Township 48 North, Range 1 East.  
Corner is a 1/2" x 48" iron pin with 2" stamped aluminum cap approximately 45 feet South of water's edge of St. Mary's River.

Witnesses:

6" Maple	S72°E	85.70 feet
12" Spruce	S58°E	86.11 feet
6" Maple	S14°E	57.36 feet
8" Ash	S12°W	46.59 feet
Steel Fence Post	North	1.0 feet

Signed by \_\_\_\_\_ Date 30 DEC 1998

Surveyor's Michigan License No. 29251

NOTE: All bearings are compass bearings corrected for declination (6°W). All distances are to a nail and tag in the side of witness object unless otherwise noted.

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971  
REVISED MAY 14, 1975  
REVISED JAN., 1983  
REVISED OCT., 1995

wp:wpdocs\larry\corner\48nr1em1.112

BOOK 10 PAGE 375

