

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970
Chippewa Co. 3 Corners

Chippewa Co.

FOR CORNERS OF--	LOCATED IN--	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY_____	T. <u>50</u> N. <u>6</u> R. <u>6</u> W.	E-11 E-12
2. PROPERTY CONTROLLING IN SECTION <u>14</u>	T. <u>50</u> N. <u>6</u> R. <u>6</u> W.	14-Sec. 33
3. MISCELLANEOUS PROPERTY IN SECTION _____	T. _____ N. _____ R. _____ E. _____	
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

REGISTER OF DEEDS STAMP AND
FILING NUMBER

I, Billy D. Buckler, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on 7-9, 1979, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

E-11 Sec. Cor. 28-29-32-33, set by Wells Burt, D.S. in 1849.
Bearings were: Cedar 6", S29°W, 13 lks. and Cedar 6", N62°E, 11 lks.
E-12 Quarter Corner bet. Sec's 32-33, set by Wells Burt, D.S. in 1849.
Bearings were: Y. Pine, 16", N62°W, 45 lks. and Y. Pine 14", S55°E, 22 lks.
14-Sec. 33 South 1/16 Corner on East side of Section 33.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

E-11 Corner set from two original witnesses, both green and in good condition.
E-12 Corner replaced from two original witnesses, stumps in proper position, also a R. Pine scribed "G.J.W." 1941".
14-Sec. 33 Corner recorded as set by R.L.S. #20706 on line and midway bet Sec. Cor. South and 1/4 Corner to North.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Placed 1" pipe with 4" aluminium cap at all corners.

E-11 New Bearings: 14" W. Pine, N70°E, 44.1' and 8" Cedar, S14°E, 22.0' and 10" Cedar, N58°W, 21.8'.
E-12 New Bearings: 8" R. Pine, N15°E, 19.2' and 14" R. Pine, N38°W, 26.35' and 6" J. Pine, S41°W, 19.65'.
14-Sec. 33 Bearings: 6" J. Pine, N07°E, 22.1' and 7" J. Pine, S34°W, 6.3' and 9" J. Pine, S81°E, 31.85'.

SIGNED BY Billy D. Buckler DATE 9-10-79
Billy D. Buckler
SURVEYOR'S MICHIGAN REGISTRATION NO. 8887



FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____
CHIEF OF SURVEY PARTY
APPROVED AND SIGNED BY _____ DATE _____
MICHIGAN REGISTERED LAND SURVEYOR

(SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. _____