95HS. 4047 NEV. 10/60

MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

LAND CORNER RECORD

			Chippewa	_ COUNTY
DESCRIPTION OF CORNER $\frac{1}{4}$	corner on sou	th side, Sec.	33, on 5th correction line	
CORNER MONUMENT 1" pipe	with 4" alumi	num cap		
DATE MONUMENT PLACED AND I	WITHESSED 6-16-	69		
VITNESSES TO CORNER	16" Red Pine	(±S 33 NBT)	N43°W 24.6°	
	12" Red Pine	(‡S 33 NBT)	N36°E 6.3°	
50-6				
CIRCLE CORNER REGISTERED	AND			<u> </u>

DESCRIPTION IN DETAIL AS TO NOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner replaced from two original witnesses, both W. Pine, bearing N4°E, 12 links and N62°W, 19 links. Both are stumps, burned and with evidence of lower face and notah.

Found no evidence of use.

Corner lies 40° south of a swamp and on high, pine land.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler DATE 8-29-69

REST STERED LAND SURVEYOR