MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

LAND CORNER RECORD

T.50. NR 6 W

•				thippew	<u> </u>
DESCRIPTION	OF	CORNER	1/4 corner between	sections 22-27	
DESCRIPTION	OF	CORNER	MONUMENT_1" pipe	with 4" brass cap	
WITTNESSES	то	CORNER	_ 4" Red Pine	\$ 20° W 1/4-5 NBT"	25 links
			4" Red Oak	_	83 links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Replaced 1/4 corner from one Y. Pine B.T. bearing N 52° E 19 links.

B.T. burned but in good condition.

Found Y. Pine stump bottom bearing S 80° W 38 links for other B.T.

Found iron pipe and wood post in place.

Corner found by B. McTiver, District Forester.

Corner placed and witnessed Dec. 12, 1957.

SURVEYORS SEAL

SIGNED Silly Suckles DATE 12-19-57