## MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

## LAND CORNER RECORD

T\_50 NR\_6W\_

		·		<b>in</b>	Ch sppeu	COUNTY
DESCRIPTION	OF	CORNER	_Section_corn	er comon to	Sec. 1s 21-2	22-27-28
DESCRIPTION	OF	CORNER	MONUMENT	_l"_pipe_with	14" brass s	2 <b>8</b> p
WITTNESSES	то	CORNER	_8" Jack Pine_	S 71	±° W 3 NBT"	25 links
			_ 9"_ Jack_Pine_	<u>\$</u> 22	<u>Р</u> 7 МЭТШ	_36 <u>links</u>
			_ 9" Jack Pine_	N 62	NBT"	_29 links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Replaced corner from one Jack Pine B.T. bearing S 64° W, 9 links. B.T. down but in good condition. Found Y. Pine stump bottom bearing N 49 E 41 links.

Corner found by B. McTiver, District Forester.

Corner placed and witnessed Dec. 12, 1957.

SURVEYORS SEAL

SIGNED Silly Suckles DATE 12/19/57