## LAND CORNER RECORDATION CERTIFICATE

## FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

Chippewa Co.

1 Corner

FOR CORNERS OF -:	LOCATE	ED IN-:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	т. <u>50</u>	_ %., R. <u>6</u> &	
2. PROPERTY CONTROLL- ING IN SECTION	,T	N. E	
3. MISCELLIANEOUS PROPERTY IN SECTION.	T.	N. E. R	
4. LOT NO , REC	CORDED PLA	AT	
5, PRIVATE CLAIMS		···	

A. Description of original monument and accessories and/or subsequent restoration:

- C-12 East 1/4 Corner of Section 31. D.N.R. L.S. Billy D. Buckler placed a 1" pipe with aluminium cap at this corner on 6-25-79. Bearings were: 8" J. Pine, S36°E, 28.3' 7" J. Pine, N54°E, 23.9' 8" J. Pine, N03°W, 41.1'
- B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:
- C-12 Buckler replaced corner from a bearing tree, NW of corner. Scribe marks were plain. Buckler's 1979 bearing trees have been cut. Marked new witt.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Re-Witt. D.N.R. Monument.

C-12 8" W. Pine, N8<sup>o</sup>W, 87.5' 8" W. Pine, N54<sup>o</sup>W, 51.8' 12" R. Pine, N86<sup>o</sup>W, 83.1' 6" Oak, S47<sup>o</sup>W, 90.0'

SIGNED BY Leval & Wiggins

SURVEYOR'S MICHIGAN REGISTRATION NO.

DATE 9-20-84

23521\_\_\_\_

GERALD L.

WIGG:NS
LAND
SURVEYOR
No.
No.
23:221