

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Chippewa
(County)

Located In:

Corner Code //

- | | | | | | |
|------------------------------------|---|-----|---|----|--------------|
| 1. Public Land Survey | T | 51N | R | 5W | A-13 |
| | T | 51N | R | 5W | 15-D-13 M.C. |
| | T | | R | | |
| | T | | R | | |
| 2. Property Controlling in Section | S | | T | | |
| | S | | T | | |
| 3. Miscellaneous Property in Sec. | S | | T | | |
| | S | | T | | |

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, Gerald L. Wiggins, in a field survey on 5-22, 19 90, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below.

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

- A-13 S.W. Section Corner of Section 31. Corner set by Hugh B. Crawford, Cadastral Surveyor for the Bureau of Land Management in 1959.
- 15-D-13 Meander Corner on the South line of Section 32. Corner set by Hugh B. Crawford, Cadastral Surveyor for the Bureau of Land Management in 1959.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

- A-13 Found monument as set by Hugh B. Crawford Cadastral Surveyor, Bureau of Land Management in 1959. Marked two new witness.
- 15-D-13 Set monument by single proportionate measure from found 8" J. Pine Bearing Tree, Bears N50°-34'W, 155.43' and a Found Concrete Monument, bearing N09°-04'- 58"W, 949.91'

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:


- A-13 B.L.M. Monument 15-D-13 D.N.R. Monument

10" Spruce, N433/4°E, 43 Lks.
 10" J. Pine, N443/4°W, 55 Lks.
 7" Spruce, S38°W, 26.2'
 10" J. Pine, N18°E, 32.8'

8" Twin J. Pine, S78°W, 44.2'
 5" J. Pine, N79°W, 72.0'
 6" J. Pine, N08°W, 94.2'
 8" J. Pine, N50°-34'W, 155.43'

Signed by Gerald L. Wiggins
 Surveyor's Michigan License No. 23521

Date 8-20-90



FORM APPROVED BY MICHIGAN REGISTER OF DEEDS, JAN. 20, 1971
 REVISED MAY 14, 1978
 REVISED JAN., 1983