

SURVEY & REMONUMENTATION

FEB 18 1994

CLARE COUNTY REMONUMENTATION PROGRAM

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

COMMISSION

For corners in

CLARE
(County)

Located In:

Corner Code ##

1. Public Land Survey

T 17N R 6W

1-11

2. Property Controlling
in Section

S T R

3. Miscellaneous
Property in Sec.

S T R

4. Lot No. , Recorded Plat

5. Private Claims

RECEIVED
FEB 18 1994
REGISTER OF DEEDS
CLARE COUNTY
DONNA M. CARR
1993 DEC 20 PM 1:45

Register of Deeds Stamp & File Number

I, MARK R. ROBISON, in a field survey on OCTOBER, 19 93,
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the
current manual of survey instructions of the United States Department of the Interior, Bureau of Land
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a
Court of Law; established, re-established, monumented, re-monumented, recovered, found as
expressed below:

**NOTE: Not more than 4 corners, all in the same town and range, may be recorded
on this certificate.**

A. Description of original monument and accessories and/or subsequent restoration:

1847 ORSON LYON, POST, PINE 13" S 60-1/2°E, 20 LKS P.318

PINE 14" S 13°W, 9 LKS

NO DATE, UNIDENTIFIED, W. PINE 30" S 40°30'W, 46 LKS CSR 6-172

W. PINE 30" N 86°E, 34 LKS

10-13-78 SEDGMAN, (132) RECORDED SURVEY, EAST, 30.05' - CORNER FENCE POST
S 55°E, 101.09' - @ 30" OAK
WEST, 33.09' - CONCRETE MONUMENT

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

FOUND 1/2" x 18" IRON IN MONUMENT BOX

FOUND RECORDED WITNESSES:

EAST, 30.05' - CORNER FENCE POST

S 55°E, 101.09' - @ 30" OAK

WEST, 33.09' - CONCRETE MONUMENT

This Corner established in Clare County Remonumentation Program.
See dossier for detailed report.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

SET 5/8" X 36" RE-ROD WITH 3" CLARE COUNTY MONUMENT CAP IN MONUMENT BOX.

N 25°W, 106.52' - 10" OAK

N 50°E, 159.25' - 36" OAK

S 60°E, 101.45' - 38" OAK

WEST, 33.09' - CONCRETE MONUMENT



Signed by

Mark R. Robison

Date

11/24/93

Surveyor's Michigan License No.

27458