

SURVEY & REMONUMENTATION

JAN 17 1996

LAND CORNER RECORDATION CERTIFICATE COMMISSION Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

CLARE

(County)

Located In:

Corner Code #

1. Public Land Survey

T 17N R 4W

A-9

T R

T R

T R

T R

2. Property Controlling
in Section

S

T R

S

T R

3. Miscellaneous
Property in Sec.

S

T R

S

T R

4. Lot No. , Recorded Plat

5. Private Claims

I, MARK R. ROBISON, in a field survey on NOVEMBER, 19 95 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

1837 JOHN HUDSON
WIT.-HEMLOCK 12" S63°W 43
BIRCH 14" N6 1/2°W 32

9-73 PAUL LAPHAM
NO WITNESSES
DRAWING OF DESCRIPTION

NO DATE, NO SURVEYOR
TILE, CINDERS & STAKE IN HWY.
B. HICKORY 8" N35°E 113 1/2

1-77 LEONARD URBANIAK (132) SURVEY
FOUND CAPPED IRON
WIT.-S80°W 134.0' 40" ELM
S35°E 41.2' 24" MAPLE
S80°E 33.0' 14" MAPLE

10-60 PAUL LAPHAM
FOUND IRON

2-77 PAUL LAPHAM UNRECORDED SURVEY
FOUND CAPPED IRON
WIT.-S80° 134.0' 40" ELM
S35°E 41.2' 24" MAPLE
S80°E 33.0' 14" MAPLE

11-77 PAUL LAPHAM L.C.R.C. 306
SAME AS ABOVE

3-82 MARK ROBISON (132) SURVEY
FOUND CAPPED IRON
SAME AS ABOVE

4-82 PAUL LAPHAM
FOUND CAPPED IRON
SAME AS ABOVE

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

FOUND 1/2"x21" RE-ROD IN MONUMENT BOX IN ASPHALT PVM'T, RETRACED UN-RECORDED SURVEY
DATED 2-1-77 AND VERIFIED THE POSITION OF THE CORNER. ALL WITNESSES GONE DUE TO
ROAD CONSTRUCTION.

APPROVED LAND CORNER

P.A. 345 of 1990

Clare County

Chairman Paul R. Robison

Date 12-12-95

This Corner established in Clare County Remonumentation Program.

See dossier for detailed report.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

A-9: 19-30 SECTION CORNER ON TOWNSHIP LINE
SET 5/8"x36" RE-ROD WITH 3" CLARE COUNTY MONUMENT CAP IN MONUMENT BOX.
ACCEPTED AS BEST AVAILABLE EVIDENCE OF THE ACCEPTED POSITION OF THE CORNER.

WITNESSES:

N80°W 108.90' - NAIL & TAG IN TWIN 20" BASSWOOD
N07°E 62.78' - NAIL & TAG IN POWER POLE
SOUTH 58.12' - NAIL & TAG IN 5" ASH
SOUTH 33.00' CAPPED IRON FROM 2-1-77 SURVEY
S35°E 72.08' - NAIL & TAG IN 28" MAPLE

Signed by

Mark R. Robison

Surveyor's Michigan License No.

27458

Date

12-13-95

