SURVEY & REMONUMENTATION

JAN 2 3 2001

LAND CORNER RECORDATION CERTIFICATE

SECTION

Signed by

Surveyor's Michigan License No. 27458

Filing Requirement of Act 74, Mich. P.A. 1970 **Clare County Remonumentation**

			200000010175
For Corners in			Filed for Record in CLARE COUNTY MICHIGAN
Clare			I CAROL MCAULAY
(County)	Located In:	Corner Code#:	On 12-15-2000 At 07:44 am.
			LAND CORNER 9.00 OR Liber 2 Page 298 - 298
1. Public Land Survey	T. <u>17N</u> R. <u>4W</u>	G-3	ON Liber & Page 236 - 256
J.	T R		
	T R		Instrument Liber Pa
2. Public Controlling	S R	· ·	200000010175 OR 2 2
in Section			
3. Miscellaneous	S R		A 503-00
	S R		
Property in Section			
	, Recorded Plat		Register of Deeds Stamp & File Number
5. Private Claims			
L			
I, Mark R. Robison, in a field survey on November 27, 2000, do hereby certify that under			
requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above			
were in conformance with regulations and rules therefore as required in the current manual or survey			
decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in 4, 7, 18, 19, 10, 11, 12			
conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of			
			8 19 20 21 22 23 24 9 +
NOTE: Not more than 2 corners, an in the same town and range, may be			
recorded on this certification	ate.		11
•			12 31 - 32 33 34 35 36
•			13
	nal monument and accessori	es and/or subsequent	
restoration:			
	•		
GLO, Burt, 1850			
Set Post			981, LCRC #401-81
Y. Pine 18" S35°W, 2 LINKS		Found 1/2" bar	
Hemlock 12" S38°E, 4 LT	NKS	Four witnesses	
CSR, Johnson, 1907, CSR	· —		
Found corner. Two witne	sses		APPROVED LAND CORNER
G-3 to G-2, 39.73 chains			P.A. 345 of 1990
G-3 to F-3, 39.50 chains	•		Clare County
0 140000 1000 11	1.10		Chairman faul B. Sephen
Survey, MDOT, 1970, Un			,
Found 1/2" iron pin in cen	iterine		Date 12-13-00
N & S & E - W Roads Four witnesses			
G-3 to F-3, 2636.88 feet			
G-3 to H-3, 2660.33 feet			,
G-5 to 11-5, 2000.55 teet			
R Description of corner a	vidence found and/or method a	applied in restoring or re-	actablishing corner
B. Description of corner c	vidence round and/or method a	applied in restoring of re-	establishing corner.
Found 1/2" v 15" iron at it	nt C I Roads Excavated & f	ound no other materials	Verified two 1970 witnesses and three 1981 witnesses.
			dence of the position of the corners.
Torrida Missor distances	to 1 5 to 11 5. Hotopica 112	iron as over avanable vin	denoted the position of the corners.
C. Description of monume	ent for corner and accessories e	established to perpetuate I	locating the position of the corner:
tott pron or monaine			O and bostmon of any activati
Set 5/8" x 36" rerod with Clare County Remon Cap marked P.S. #27458.			
Witnesses:			
N45°E, 40.14' - Fd N & T in Cor. Fence Post (OBT)			
S45°E, 51.96' - Cen. Tele	. ,	OF MIC.	
S74°W, 55.96' - N & T in Gate Post			
N45°W, 45.87' - Cen. Tele Riser MARK R			
N*/ ROBISON \"N			
		NE PROFESSIONAL	

SURVEYOR

Date

551011 FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983