

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF--	LOCATED IN--	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 18 N. R. 06 W.	A-4, C-4
2. PROPERTY CONTROLLING IN SECTION	7, T. 18 N. R. 06 W.	3,
3. MISCELLANEOUS PROPERTY IN SECTION	8, T. 18 N. R. 06 W.	1353.1' S OF C-3 969.7' N OF C-4
4. LOT NO.	, RECORDED PLAT	
5. PRIVATE CLAIMS		

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, CARL F. ROSER, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on JANUARY 31, 1985, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

C. (CONTINUED)

XX

FD 1 1/4" PIPE W/RLS CAP; ADDED CED POST W/LOC TAG.	FD 1 1/4" PIPE W/RLS CAP; ADDED CED POST W/LOC TAG.
15" MAPLE N30°W 2.3'	6" OAK N70°E 16.9'
6" OAK N80°E 13.8'	4" MAPLE S35°E 19.1'
CTR M115 DUE S 103'	CTR M115 DUE N 103'
4"X4" CONC	4"X4" CONC
R/W MARKER S45°E 25.8'	R/W MARKER S45°E 29.9'

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

- A-4 FD & ACCEPTED 1/2" ROD BY RLS, PAUL LAPHAM FOR W 1/4 COR OF SEC 7.
- C-4 FD 1 1/4" IR BY RLS, M. MCCLUNG, FOR W 1/4 COR OF SEC 8.
- 3 FD AND ACCEPTED 1/2" ROD BY RLS, PAUL LAPHAM FOR SW COR OF NW 1/4 OF NW 1/4 OF SEC. 7.
- * FD 1 1/4" PIPE W/RLS CAP, M. MCCLUNG, ON INTERSEC. OF W. LINE OF SEC 8 & NORTHERLY R.O.W. LINE OF M115.
- ** FD 1 1/4" PIPE W/RLS CAP, M. MCCLUNG, ON INTERSEC OF W LINE OF SEC 8 & SOUTHERLY R.O.W. LINE OF M115.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

A-4	C-4	3
FD 1/2 X 18" REROD W/RLS CAP; ADDED DNR MON & CED POST.	FD 1 1/4 X 25" STEEL SHAFT, ADDED DNR MON & CED POST.	FD 1/2" REROD W/RLS CAP; ADDED CED POST W/LOC TAG.
8 MAPL CLUMP 3 N50°W 22.8'	7" CEDAR N30°W 37.7'	3" ASH N45°W 30.6'
9" MAPLE N20°E 4.1'	5" CEDAR N10°E 7.8'	2" ASH N20°E 37.1'
6" ASH S65°E 13.8'	20" W PINE N25°E 50.4'	8" W BIRCH N40°E 25.7'
18 MAPL CLUMP 6 S30°E 28.7'	4" BALSAM S80°E 18.9'	CROOKED TRL
		N'LY DUE W 25'
		CTR CREEK DUE S 173'

SIGNED BY Carl F. Roser

DATE 01-13-86

SURVEYOR'S MICHIGAN REGISTRATION NO. 12028

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____

DATE _____

CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY _____

DATE _____

MICHIGAN REGISTERED LAND SURVEYOR

(SEAL)

FREEMAN TWP
CLARE COUNTY

SURVEYOR'S MICHIGAN REGISTRATION NO. _____