

JAN 27 2000

SECTION

LAND CORNER RECORDATION CERTIFICATE  
CLINTON COUNTY REMONUMENTATION  
SECTION CORNER COMMON TO SECTIONS 18 AND 19, T5N-R2W  
DEWITT TOWNSHIP  
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Clinton (County)	Located in:	Corner Code #
1. Public Land Survey	T 5N R 2W	A-7
	T R	
	T R	
	T R	
2. Property Controlling In Section	S T R	
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. _____, Recorded Plat _____		
5. Private Claims _____		

LIBER 004 PAGE 343  
RECORDED

Dec 21 12 49 PM '99

REGISTERED DEEDS  
CLINTON COUNTY, MICH.  
Register of Deeds Stamp  
& File Number

I, Mark L. VanRaemdonck, in a field survey on, June 10, 1999, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below:

**NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.**

A. Description of original monument and accessories and/or subsequent restoration:

1. Original, Hervey Parke, D.S., 1827.  
Monument: Wood Post, intersected range line 10 South.  
Accessories: Beech 9 N12°E 42 1/2'  
W. OAD 30 S47°E 80'
2. Douglas W. Hooth, L.C.R.C., recorded Liber 2, page 52, June 7, 1976.  
Monument: Found 1/2" Copperweld in monument box.  
Accessories: N40°E tele. pole 49.58'  
N30°W tele. pole 63.67'  
N50°W tele. pole 77.06'  
S40°W 19" Maple 54.28'  
Sketch shows corner M-7, T5N-R3W, North 6.60 feet.
3. Marvin F. Fouty, Certified Survey, recorded Liber 1, page 811, September 7, 1976.  
Monument and accessories same as No. 2 above.
4. M.D.O.T. plans for project I-69 -3 (33) 83, July 2, 1981.  
Monument and accessories same as No. 2 above.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

Found Copperweld in monument box as referenced in No. 2 above. Found corner M-7, T5N-R3W, 6.62 feet North in accordance with the G.L.O. notes. This location is 0.24 feet East of the Standard Township Line. Found no conflicting evidence and accepted this location as the original corner position based on the best available evidence.

C. Description of monument for corner and accessories to perpetuate locating the position of the corner:

Set a standard Clinton County Remonumentation monument, being a 2 1/2" diameter steel tube, 30" long with a standard brass cap, stamped "P.S. 24622", and a breakaway magnetic base at the corner location described in Section B above. The monument is witnessed by the following accessories:

S35°E 58.57' Fnd. N&T NE face util. Pole  
S35°W 54.40' Fnd. N&T NW face 18" Maple  
N35°W 66.79' Fnd. N&T SW face util. Pole  
N25°E 72.54' Set N&T W. face util. Pole  
N00°10'47"E 6.62' Remon Monument at M-7  
S00°10'47"W 2638.23' Remon Monument at M-8

Bearings to M-7 and M-8 are based on solar observations.

Signed by Mark L. VanRaemdonck  
Surveyor's Michigan License No. 24622

Date 12-16-99

