

SURVEY &
REMONUMENTATION

MAY 05 1997

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

COMMISSION

(County)

Located In:

Corner Code #

1. Public Land Survey

T 25 R 2W

E-13

T _____ R _____

T _____ R _____

T _____ R _____

2. Property Controlling
in Section

S _____ T _____ R _____

S _____ T _____ R _____

3. Miscellaneous

S _____ T _____ R _____

Property In Section

S _____ T _____ R _____

4. Lot No. _____, Recorded Plat _____

5. Private Claims _____

LIBER

3

PAGE

248

I, Marvin E. Myers, P.S., in a field survey on Nov. 21, 1996, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

GLO-June 1852 W. Burt
Mon-Post

L.163, P.550 F.J.Arleth 1977
Mon-3/4" Bar

L.3, P.35 M.E.Myers 1991
Mon- 3/4" Bar

Wit-8" P. Pine N53°W 68 Lks

Wit-1' South of edge of pav't

Wit-Face of utility pole S40°W 18.08

7" P. Pine N52½°E 27 Lks

12" Pine N42½°E 91.30

NE Corner "Dan's Flies" Sign Post S45°E 27.03

12" Spruce pine N30°E 78 Lks

15" R. Pine N10½°W 104.10

15" R. Pine N10½°W 104.10

12" Spruce Pine N42°W 79 Lks

E. Edge Stop Sign post N02°W 51.80

G.D. Henning & R.T. Ostling 1949
Mon-5/8" Iron bar

L.186, P. 36 N.F. Parker 1980
Mon-none given
Wit-none given

R.T. Ostling 1961, 1963, 1973
Mon-3/4" Bar

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 3/4" Bar on South side of road 1½ South of edge of pavement; found 1" bar along side 3/4" Bar

Found Utility Pole S40°W 18.08

Found 15" R. Pine N10½°W 104.10

Accepted as the best available evidence of the position of the original corner

CRAWFORD COUNTY

PEER GROUP APPROVAL

DATE NOV 22 1996

Marvin E. Myers
Marvin E. Myers, P.S.
County Surveyor

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Replaced with Standard Roscommon County Monument

Wit: Nail & tag in "Deerheart Valley Road" Sign Post N50°E 66.98

Nail & tag in Telephone pole N48°W 72.04

Nail & tag in Telephone Pole S44°W 18.38

4" B. Oak S58°E 85.48



Signed by

Marvin E. Myers

Date

Dec 14, 1996

Surveyor's Michigan License No.

31600

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1975
REVISED JAN., 1983