LAND CORNER RECORDATION CERTIFICATE

	Filing Requir	ement of Act 74, Mich.	PA 1970	
For Corners In: Crawford (County)	Located In	Corner Code #	18	
Public Land Survey	T _25N _ R 3W	K-1	/1 //	
Property Controlling in Section	T 25N R 3W S T R	<u>L-1</u>	eŭ.	
Miscellaneous Property in Section	S T R S T R		Register of Deeds Stamp & File Number	
4. Lot No:	Recorded Plat:		ABCDEFGHIJKLM	
5. Private Claims:			A B C D E F G H I J K L M	
I, <u>Carl T. Kiiskila</u> , in a field survey on <u>July 28 ,2010</u> do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below: NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.				
A. Description of original monument and accessories and/or subsequent restoration:				
K-1 Sec. cor. comm. t sec.'s 35,36, T26	o sec.'s 1,2, T25N, R03W & 6N, R03W	<u>L-1</u> Quarter section	cor. comm. to section 1, T25N, R03W & 36, T26N, R03W	
P.S.#17614 – Fd. 3 remove. Set stand 17614, 1997. Nail and tag in P.I Nail and tag in 10" Nail and tag in 18" I	- L.3, p.278 - Larry L. Cavanagh 3/4"x12" pipe over 1 ½" pipe could lard Crawford Co. monument stan Pole N70°E 102.25' Maple N30°W 77.34' B. Oak S42°E 96.81' B. Oak S39°W 91.71' 45°E 63.22'	not P.S.#1 17614 Nail and Nail and Nail and Nail and 1/2" Bar	on L.C.R.C. – L.3, p.279 – Larry L. Cavanagh, 7614 Set standard Crawford Co. monument stamped from Kenneth J. Ostling P.S. 10068 1979 Witnesses. It tag in P. Pole S41°E 22.72' It tag in 9" J.Pine S38°W 27.63' It tag in 9" J.Pine S3°E 23.06' It tag in 34" B. Oak N76°W 114.61' N02°E 34.41' Ite Post South 21.55'	
B. Description of corner evidence found and/or method applies in restoring or re-establishing corner:				
<u>K-1</u> Sec. cor. comm. to 35,36, T26N, R03	o sec.'s 1,2, T25N, R03W & W		cor. comm. to sec.'s 1, T25N, R03W & N, R03W	
Found Crawford Co. monument per L.C.R.C., L.3, p.278. In mon. box Corner falls in c/l of road intersection. One witness to SE was gone, so added new witness. Accepted as the best available evidence of the position of the original corner.		tness to Corner fall best Accepted :	Found Crawford Co. monument per L.C.R.C., L.3, p.279 Corner falls 1' South of E-W c/l gravel road 6" below grade. Accepted as the best available evidence of the position of the original corner.	
C. Description of monume	ent for corner and accessories est	ablished to perpetuate lo	cating the position of the corner:	
<u>K-1</u> Sec. cor. comm. to 35,36, T26N, R03	o sec.'s 1,2, T25N, R03W & W	<u>L-1</u> Quarter	cor. comm. to sec.'s 15 & 22, T25N, R03W	
Standard Crawford Co Witnesses: * Fd Nail and tag SE * Fd Nail and tag SV * Fd Nail and tag S Set Nail and tag SW	unty Monument side P. Pole N70°E 102.20' Vide 11" Maple N30°W 77.34' E side 15" B. Oak S39°W 91.72' side 14" & 12" Twin R. Pine S66°I	Witnesses: Fd Nail Set Nai Set Nai * Fd Ni E 95.80' Fd ½" Set Nail * Previ	crawford County Monument and tag SE side P. Pole N24°E 35.95′ I and tag NE side Guy. Pole S46°E 23.10′ I and tag SE side 10″ J. Pine S34°E 27.90′ ail and tag S side 37″ B. Oak N78°W 114.66′ Bar N02°E 41.71′ and tag SW side 4″ J. Pine N 40°W 67.45′ ous recorded witness	
Signed by:	and T Kriski	La Date:	9-7-10 A KHSKILA	
Surveyor's Michigan Li	7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7		LAND SURVEYOR No. 33981	
	FC	ORM APPROVED BY MICHIGA	STATE BOARD OF PROFESSIONAL SURVEYING SHIP 25, 1971 Revised May 14, 1975 Revised Jan. 1983	

75 34 28, 1971 vised May 14, 1975 Revised Jan. 1983 Revised Oct. 1995