

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. PA 1970

For Corners In: _____ Located In _____ Corner Code # _____
Crawford _____
(County)

1. Public Land Survey	T	28N	R	3W	E-7
	T	28N	R	3W	E-8
2. Property Controlling in Section	S	_____	T	_____	R
	S	_____	T	_____	R
3. Miscellaneous Property in Section	S	_____	T	_____	R
	S	_____	T	_____	R

4. Lot No: _____ Recorded Plat: _____
5. Private Claims: _____

I, Carl T. Kiiskila, in a field survey on August 11, 2008 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6			5		4		3		2		1	
3													
4	7			8		9		10		11		12	
5													
6	18			17		16		15		14		13	
7													
8	19			20		21		22		23		24	
9													
10	30			29		28		27		26		25	
11													
12	31			32		33		34		35		36	
13													

A. Description of original monument and accessories and/or subsequent restoration:

E-7 G.L.O. Walter Warner 1856 reestablished old corner of sections 16,17,20 and 21. Wit: Beech 8 N51°E 21 links Beech 8 S58°30'E 25 links 1970 Kenneth J. Ostling R.L.S. #10068 found a RR iron of long standing acceptance at corner. Wit: Maple 32" N55°W 51.0' Maple 23" S81°W 54.9'	E-8 G.L.O. Walter Warner 1856 reestablished old quarter section corner. Wit: Birch 15 S15°E 20 links Elm 18 N56°W 17 links 1970 Kenneth J. Ostling R.L.S. #10068 set corner by proportionate measurement with the U.S. record deflection. Wit: Tw. R. Pine 8" S70°W 37.8' Tw. R. Pine 12" S41°W 62.5'
--	--

B. Description of corner evidence found and/or method applies in restoring or re-establishing corner:

E-7 Found ½" iron in a monument box fitting K.J. Ostling's survey in section 20.	E-8 Found ½" iron rod fitting one of K.J. Ostling's witnesses and his survey in section 20.
--	---

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

E-7 Found ½" Iron Wit: Found nail and tag #43046 in South side of a 40" Maple S85°W 56.03' Set nail and tag in Southwest side of a 18" Maple N43°W 53.55' Set nail and tag in South side of a 6" White Pine N44°E 52.13' Set nail and tag in Southeast side of a 10" Maple S12°E 82.77'	E-8 Set 1" X 48" iron pipe with P.S. cap #33981 Wit: Set nail and tag in North side of a 7" White Pine N73°E 54.65' Set nail and tag in North side of a 10" Jack Pine S72°E 58.70' Set nail and tag in North side of a 12" twin Red Pine S75°W 38.38' Set nail and tag in Northeast side of a 6" Cherry N54°W 76.79' Set Carsonite Post West 33'±
---	--

Signed by: _____

Carl T. Kiiskila

Surveyor's Michigan License No.: _____

33981

Date: _____

6-23-09

