STATE OF MICHIGAN DEPARTMENT OF NATURAL RESOURCES

LAND CORNER RECORD

| | | <u>CRAWFORD</u> COUNTY | |
|--|-------------------------------|------------------------|---------|
| | | T26 | N R 1 W |
| DESCRIPTION OF CORNER | 1/16 corner at Center | of SE 1/4, Sec. 3 | |
| CORNER MONUMENT | Set 1"x36" Pipe | | |
| DATE MONUMENT PLACED AND WITNESSED 1-28-71 | | | |
| WITNESSES TO CORNER | | | |
| Sec. 3 | 5" J. Pine | N 15 W | 24.3' |
| 0 | <u>10" Oak</u> AN D | S 35 W | 22.0' |
| CIRCLE CORNER REGISTERED | | | |

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was set by standard survey procedure for the subdivision of sections, to mark state land boundary. Concrete tile monument set in unofficial local survey is 5.3 West and 8.1 South of proper subdivisional position.

SURVEYOR'S SEAL

DISTRIBUTION: SIGN

GNED Mundly Hall

2/9/71

REGISTERED LAND SUI

10068

County Courthouse Area Forester (Regions I & II) District or Region Surveyor Forestry Div., Lansing