

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 26. NR. 1 W.

Crawford

COUNTY

DESCRIPTION OF CORNER Section Corner common to Sections 13, 14, 23, 24

DESCRIPTION OF CORNER MONUMENT 1" Pipe with 4" Brass cap

WITNESSES TO CORNER

9" J. Pine - S 73 E - 44 Links

12" J. Pine - S 45 W - 93 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found by Forestry Division survey crew, while making a partial resurvey of this Township. Two original B.T.s still in place, in poor condition. A 1/2" Tree Bar has been placed about 10' SW of corner, erroneously, I believe.

Corner was placed and witnessed November 6, 1953.

SURVEYORS SEAL

SIGNED John C. DeBorja DATE 1/27/54
REGISTERED LAND SURVEYOR