

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. PA 1970

For Corners In:
Crawford
(County)
Located In
Corner Code #

1. Public Land Survey
2. Property Controlling in Section
3. Miscellaneous Property in Section
4. Lot No:
5. Private Claims:

I, Carl T. Kiiskila, in a field survey on October 10, 2005 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

Register of Deeds Stamp & File Number

Table with 13 rows and 13 columns (A-M). Contains numerical data for survey points, with some cells containing numbers like 6, 5, 4, 3, 2, 1, 7, 8, 9, 10, 11, 12, 18, 17, 16, 15, 14, 13, 19, 20, 21, 22, 23, 24, 30, 29, 28, 27, 26, 25, 31, 32, 33, 34, 35, 36.

A. Description of original monument and accessories and/or subsequent restoration:

M-3 G.L.O. B. Mullett 1849 set post for corner of sections 1,6,7,and 12.
Wit: Pine 8" N77°W 13 links
Pine 8" S22°W 24 links
7- This corner position was not established during the original government survey.

December 1954 Kenneth J. Ostling R.L.S. #10068 found remains of three original B.T.'s still in place in poor condition
added 1" Pipe with 4" brass cap
Wit: 12" J. Pine N25°W 16 links
20" R. Pine S89°E 206 links

B. Description of corner evidence found and/or method applies in restoring or re-establishing corner:

M-3 Found DNR monument as set by K. J. Ostling.
7- Established the Northeast corner of the Southeast quarter of the Northeast quarter of section 12 as per B.L.M. instructions for the subdivision of a section.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

M-3 1" Pipe with 4" brass cap
Wit: 12" W. Pine S84°W 4.46'
P. Pole N03°E 21.46'
6" R. Pine S71°E 23.74'
20" R. Pine S10°W 42.88'
7- Set 5/8" X 32" iron rod with P.S. cap #33981
Wit: 6" Cedar N41°E 22.17'
5" Cedar S42°E 16.66'
5" Tamarack S62°W 5.84'
6" Cedar N16°W 29.81'
1/2" iron N06°E 6.62'
Blue Carsonite post East 1±

Signed by:

Carl T. Kiiskila

Date:

11/28/05

Surveyor's Michigan License No.:

33981

