

SURVEY &  
REMONUMENTATION

APR 07 1998

LIBER  
LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

3 PAGE 284

For corners in

SECTION

Crawford

(County)

Located In:

Corner Code #

1. Public Land Survey

T. 26N R. 2W

C-3

2. Property Controlling  
in Section

S

T

R

3. Miscellaneous  
Property in Sec.

S

T

R

4. Lot No. , Recorded Plat

5. Private Claims

STATE OF MICHIGAN  
CRAWFORD COUNTY  
RECORDED

19 DEC 97 2:37 P.M.

SANDRA MOORE  
REGISTER OF DEEDS

Register of Deeds Stamp & File  
Number

LIBER

3

PAGE

2

I, Marvin E. Myers, in a field survey on 27 MAY, 1997 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

**NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.**

A. Description of original monument and accessories and/or subsequent restoration:

G.L.O. 15 June 1852

Darwin A. Pettibone D.S.

Mon: Post

Wit: 7" Pine N19°W 5 links

12" Pine N65°E 31 links

George D. Henning R.L.S.

Unrecorded Survey Sec. 5 T26N R2W Oct 1955

Mon: set 4" Concrete monument

Wit: 10" J. Pine N10°W 52.7

5" J. Pine S28 ½°E 66.7'

6" J. Pine S27 ½°W 52.5

Old fence corner 30' East

George D. Henning R.L.S.

Unrecorded Survey Sec. 6 T26N R2W Oct 1956

Mon: set 4" Concrete monument

Wit: 10" J. Pine N10°W 52.7

5" J. Pine S28 ½°E 66.7'

6" J. Pine S27 ½°W 52.5'

Old fence corner 30' East

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: Found concrete monument no evidence of Henning witnesses due to fire. This position was accepted as the best available evidence of the position of the Original corner. Found spike South face 6" Jack Pine N70°E 84.95"; found spike East face Utility Pole S03°E 101.38'. Replaced concrete monument with Standard Crawford County Monument. Found ½" bar in centerline of trail road N89°E 28.63' **This position was not accepted.**

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Mon - Standard Crawford County Monument

Wit: Found spike South side 6" Jack Pine N70°E 84.95"

Found spike in East side Utility Pole S03°E 101.38'.

Set spike South side 6" Jack Pine N11°E 276.93'

Found ½" bar in centerline of trail road N89°E 28.63'

CRAWFORD COUNTY  
PEER GROUP APPROVAL  
DATE OCT 16, 1997

Marvin E. Myers

Marvin E. Myers, P.S.  
County Surveyor

Signed by

Surveyor's Michigan License No. 31600

Date

Dec 15, 1997