

# LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF --:	LOCATED IN --:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY _____ T. 27 N. R. 1 W.		A-5; A-7; A-9; C-5
2. PROPERTY CONTROLLING IN SECTION _____, T. _____ N. S. R. _____ E. W.		
3. MISCELLANEOUS PROPERTY IN SECTION _____, T. _____ N. S. R. _____ E. W.		
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Kenneth J. Ostling do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram - over) were, in a field survey on December 6, 1974, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on 19, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

- B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:
- A-5 Found corner as restored by Schaaf in 1934 survey from U.S.B.T.'s.
  - A-7 Found corner as restored by Schaaf in 1934 survey from U.S.B.T.'s.
  - A-9 Found corner as restored by Schaaf in 1934 survey from U.S.B.T. stump.
  - C-5 Found corner as restored in 1934 survey by M. Schaaf from U.S.B.T.'s.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

A-5	A-7	A-9
1 1/2" pipe set in conc. red-top post 30'SE	1 1/2" pipe in conc. red-top post	1 1/2" pipe in conc. red-top post 10'E
14" R. Pine S30°E 32.9	4" R. Pine N40°W 29.4	9" R. Pine S85°W 17.2
7" R. Pine N44°E 41.4	5" R. Pine N50°E 61.65	9" R. Pine S26°W 29.85
C-5		
1 1/2" pipe in conc. mon. red-top post 22' SW		
12" R. Pine N65°E 33.9		
8" R. Pine S23°E 28.3		


SIGNED BY Kenneth J. Ostling DATE \_\_\_\_\_

SURVEYOR'S MICHIGAN REGISTRATION NO. 10028

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY \_\_\_\_\_ DATE \_\_\_\_\_  
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY \_\_\_\_\_ DATE \_\_\_\_\_  
MICHIGAN REGISTERED LAND SURVEYOR



(SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. \_\_\_\_\_

CRAWFORD COUNTY