

# LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners in:

Crawford

(County)

Located In

Corner Code #

1. Public Land Survey T 28N R 3W K-12  
T  
2. Property Controlling in Section S T R  
S T R  
3. Miscellaneous Property in Section S T R  
S T R

4. Lot No: Recorded Plat:

5. Private Claims:

I, Carl T. Kiiskila, in a field survey on December 23, 2008 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

K-12 1857 - GLO - Walter Warner - Set quarter section post. Cedar 5 S80°W 11 links  
W.Pine 9 N72°E 12 links  
1986 - Certificate of Survey - L.255, pg.189 - Norman F. Parker P.S.#16939 - Set 1/2"x18"CIR by single proportion. 4" Spruce S45°E 3.60'  
3" Spruce N45°E 8.60'  
6" Birch S85°W 7.45'

1999 - Certificate of Survey - Ronald C. Brand P.S.#43046 - Found bar and cap#16939.  
Set N&T E. side 3" Spruce S25°E 24.03'  
Set N&T N. side dead 4" blazed Spruce N40°E 9.11'  
Set N&T N. side dead 12" Cedar N67°E 57.38'  
Set N&T S. side 8" dead Cedar 47.31'  
Fd. blazed dead 6" Birch S85°W 4.86'  
1999 - L.C.R.C. - L.4, pg.62 - Ronald C. Brand P.S.#43046 - Same information as above. Measures distances to North and East both of which compare well with Parker's survey.

B. Description of corner evidence found and/or method applies in restoring or re-establishing corner:

K-12 Quarter corner common to secs. 35 & 36, T28N,R3W

Found 1/2"x18" CIR#16939 below water in dead cedar and spruce swamp. Replaced found CIR with stamped 4" aluminum DNR cap on 1"x7' galvanized pipe and is accepted as careful and faithful reestablishment of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

K-12 4" aluminum DNR cap on 1"x7' galvanized pipe  
Wit.N63°E 57.41' to fd. N&T on N side 11" Dead Cedar  
S30°E 24.04' to fd. N&T on E side 3" Spruce  
N34°W 45.94' to set N&T on W side 5" Dead Cedar stump  
S70°W 37.66' to set N&T on N side 2" Spruce  
Set Blue Carsonite Post 1' North



Signed by:

Carl T. Kiiskila

Date:

1-6-10

Surveyor's Michigan License No.:

33981