

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In:

Crawford

(County)

Located In

Corner Code #

1. Public Land Survey	T	_____	R	_____	_____
	T	_____	R	_____	_____
2. Property Controlling in Section	S	26	T	28N	R 3W 6
	S	26	T	28N	R 3W 9
3. Miscellaneous Property in Section	S	_____	T	_____	R _____
	S	_____	T	_____	R _____

Register of Deeds Stamp & File Number

4. Lot No: _____ Recorded Plat: _____

5. Private Claims: _____

I, Carl T. Kiiskila, in a field survey on January 12, 2009 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6			5		4		3		2		1	
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

6 - NE 1/16 Cor., Section 26, T28N, R3W

9 - CE 1/16 Cor., Section 26, T28N, R3W

Unknown date - Survey Map - Norman F. Parker P.S.
#16939 - Shows 1/2"x18" iron bar for corner.
N84°E 41.4' to 4" Maple
N42°E 57.9' to 6" Twin Maple

None

B. Description of corner evidence found and/or method applies in restoring or re-establishing corner:

6 - NE 1/16 Cor., Section 26, T28N, R3W

9 - CE 1/16 Cor., Section 26, T28N, R3W

Searched for Parker's corner but found no evidence. Set 5/8"x34" CIR#33981 per standard BLM procedure. Found no other evidence to dispute the location for the corner. East 16' to centerline of N-S trail.

Set 5/8"x34" CIR#33981 per standard BLM procedure. Found no other evidence to dispute the position of the corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

6 - NE 1/16 Cor., Section 26, T28N, R3W

9 - CE 1/16 Cor., Section 26, T28N, R3W

5/8"x34" CIR#33981

Wit: N15°E 29.58' to set N&T on W side 8" Elm
N62°W 24.37' to set N&T on S side 7" W.Pine
S71°E 5.32' to set N&T on S side 5" W.Pine
S57°W 28.32' to set N&T on W side 10" Twin W.Pine
Set Blue Carsonite Post w/loc. tag 1' North

5/8"x34" CIR#33981

Wit: N12°E 36.94' to set N&T on W side 8" White Pine
S40°E 43.27' to set N&T on NE side 14" W.Pine
N84°W 47.26' to set N&T on S side 12" Elm
S73°E 56.17' to set N&T on N side 5" W.Pine
Set Blue Carsonite Post w/loc. tag 1' North

Signed by:

Carl T. Kiiskila

Date:

1-6-10

Surveyor's Michigan License No.:

33981

