

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In:

Crawford

(County)

Located In

Corner Code #

1. Public Land Survey T _____ R _____
T _____ R _____
2. Property Controlling in Section S 20 T 28N R 3W 7
S _____ T _____ R _____
3. Miscellaneous Property in Section S _____ T _____ R _____
S _____ T _____ R _____

4. Lot No: _____ Recorded Plat: _____

5. Private Claims: _____

I, Carl T. Kiiskila, in a field survey on August 11, 2008 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

Register of Deeds Stamp & File Number

| | A | B | C | D | E | F | G | H | I | J | K | L | M |
|----|----|---|----|---|----|---|----|---|----|---|----|---|---|
| 1 | | | | | | | | | | | | | |
| 2 | 6 | | | 5 | | 4 | | 3 | | 2 | | 1 | |
| 3 | | | | | | | | | | | | | |
| 4 | 7 | | 8 | | 9 | | 10 | | 11 | | 12 | | |
| 5 | | | | | | | | | | | | | |
| 6 | 18 | | 17 | | 16 | | 15 | | 14 | | 13 | | |
| 7 | | | | | | | | | | | | | |
| 8 | 19 | | 20 | | 21 | | 22 | | 23 | | 24 | | |
| 9 | | | | | | | | | | | | | |
| 10 | 30 | | 29 | | 28 | | 27 | | 26 | | 25 | | |
| 11 | | | | | | | | | | | | | |
| 12 | 31 | | 32 | | 33 | | 34 | | 35 | | 36 | | |
| 13 | | | | | | | | | | | | | |

A. Description of original monument and accessories and/or subsequent restoration:

7-1970 Kenneth J. Ostling R.L.S. #10068 set a
1"x 36" pipe for the corner.
Wit: 11" Beech S63°W 54.9'
7" Maple N82°W 32.8'

B. Description of corner evidence found and/or method applies in restoring or re-establishing corner:

7- Found 1" pipe fitting Kenneth J. Ostling witnesses and survey in section 20.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

7- Found a 1" pipe set a 5/8" X 12" iron rod W/P.S. cap
#33981 in center
Wit:
Set nail and tag in South side 9" Tw. Maple S44°E 52.36'
Set nail and tag in North side 13" Maple N79°W 32.42'
Set nail and tag in North side 14" Maple N59°W 45.29'
Set nail and tag in North side 12" Beech N75°E 58.09'



Signed by:

Carl T. Kiiskila

Date:

6-23-09

Surveyor's Michigan License No.:

33981