

# LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In:

Crawford  
(County)

Located In

Corner Code #

- |                                      |   |    |   |             |
|--------------------------------------|---|----|---|-------------|
| 1. Public Land Survey                | T |    | R |             |
|                                      | T |    | R |             |
| 2. Property Controlling in Section   | S | 21 | T | 28N R 4W 8  |
|                                      | S | 21 | T | 28N R 4W 10 |
| 3. Miscellaneous Property in Section | S |    | T | R           |
|                                      | S |    | T | R           |

4. Lot No: \_\_\_\_\_ Recorded Plat: \_\_\_\_\_

5. Private Claims: \_\_\_\_\_

I, Carl T. Kiiskila, in a field survey on December 5, 2005 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

**NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.**

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

8- Liber 197, page 219, 1980 C. Eugene Ostling R.L.S.  
#12026 Set 1/2" bar for corner. No witnesses given.

10- Liber 197, page 219, 1980 C. Eugene Ostling R.L.S.  
#12026 Set 1/2" bar for corner. No witnesses given.

B. Description of corner evidence found and/or method applies in restoring or re-establishing corner:

8- Found 1/2" bar with R.L.S. cap #12026 fitting C. Eugene Ostling survey of section 21.

10- Found 1/2" bar with R.L.S. cap #12026 fitting C. Eugene Ostling survey of section 21.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

8- Placed P.S cap #33981 on found 1/2" bar.

Wit: 20" Oak	N25°E	30.62'
30" Maple	S12°E	44.37'
Corner of Fence Post	S59°E	56.90'
8" Cherry	S82°W	41.30'
Blue Carsonite Post	North	1'±

10- Placed P.S. cap #33981 on found 1/2" bar.

Wit: 6" Twin Maple	N01°E	28.02'
6" Elm	N45°W	36.50'
14" Maple	N50°E	52.68'
Fence post	S56°W	42.63'
E-W Fence	North	30'
N-S Fence	West	30'
Blue Carsonite Post	North	1'±

Signed by:

Carl T. Kiiskila

Date:

12/20/05

Surveyor's Michigan License No.:

33981

