

# LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In:

Crawford

(County)

Located In

Corner Code #

1. Public Land Survey	T		R	
	T		R	
2. Property Controlling in Section	S 27	T 28N	R 4W	12
	S 27	T 28N	R 4W	13
3. Miscellaneous Property in Section	S	T	R	
	S	T	R	

4. Lot No: Recorded Plat:

5. Private Claims:

I, Carl T. Kiiskila, in a field survey on November 1, 2005 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

**NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.**

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

12- May 30, 1975 Kenneth J. Ostling R.L.S. #10068 set a 1" x 30" pipe by standard procedure for subdivision of a section.

13- Liber 153, Page 460 (1976) George D. Henning R.L.S. #2240 set a 1/2" bar for corner.  
No witnesses given

Wit: 10" Maple S60°W 6.8'  
7" Maple S08°E 22.65'  
1/2" Iron Rod S50°E 18.25'

B. Description of corner evidence found and/or method applies in restoring or re-establishing corner:

12- Found 1" pipe fitting K.J. Ostling's witnesses.

13- Found 1/2" bar with R.L.S. cap #2240 fitting G.D. Henning's survey in section 27.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

12- Found 1" pipe  
Wit: 14" Maple S52°W 7.28'  
12" Maple N53°W 7.44'  
10" Maple S08°E 22.73'  
9" Maple clump N67°E 34.15'  
Centerline of North/South Road East 63'±  
Carsonite Post North 1'±

13- Found 1/2" bar with P.S. cap #2240  
Wit: 8" Cherry S26°W 18.40'  
11" Cherry S84°W 70.97'  
5" W. Pine N30°W 22.00'  
Carsonite Post North 1'±

Signed by:

Carl T. Kiiskila

Date:

11/30/05

Surveyor's Michigan License No.:

33981

