

MAR 29 2000

SECTION

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Crawford

(County)

Located In:

Corner Code #

1. Public Land Survey

T 28N R 4W

E-11

T \_\_\_\_\_ R \_\_\_\_\_

T \_\_\_\_\_ R \_\_\_\_\_

T \_\_\_\_\_ R \_\_\_\_\_

2. Property Controlling  
in Section

S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_

S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_

3. Miscellaneous  
Property in Sec.

S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_

S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_

5. Private Claims \_\_\_\_\_

LIBER

4 PAGE

63

I, Marvin E. Myers, in a field survey on July 22, 1999, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

G.L.O - 1856 W. Warner, DS

L1, P64 LCRC Nov 5, 1973 K. Ostling #10068

Mon - Old gr. Sec. Cor. Reestablished

Mon - Reestablished by Dbl. Proportionate

Wit: 9" Beech N41°E 7 lks.

Set DNR Mon & red top Post

5" Beech S27°W 35 lks.

Wit: 5" Tw. Maple N19°E 26.8

7" Maple S65°W 6.5

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found DNR mon with red top post; found 5" tw. Maple (stump) N19°E 26.8; found 7" (now 10") Maple S65°W 6.5 Accepted DNR Monument as a reestablisher of the position of the Original Government Corner. Left DNR Monument in place.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Mon - DNR Monument left in place

Wit: Set carsonite post S08°W 0.43

10" Maple S65°W 6.5

8" Poplar N22°E 12.09

3" Poplar N29°W 19.61

CRAWFORD COUNTY

PEER GROUP APPROVAL

DATE NOV 30, 1999

Marvin E. Myers

Marvin E. Myers, P.S.  
County Surveyor



Signed by

Marvin E. Myers

Surveyor's Michigan License No. 31600

Date 12-06-1999